



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI24100352/Enp3e2
(BUDGET DIRECT INSURANCE) Date: 17/12/2024
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE SINGAPORE 239924 Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGB 2209J	Veh. Inspected	FBT 2722H
Policy No.	P11099808R00	Coverage	0
Claim No.	C10031856/JK	Excess	\$0.00
Assign From	JANICE KOH	Assign Date	21/10/2024

2. Vehicle Details

Make & Model	K.T.M. 200 DUKE	C.C	200
Engine No.	L93604065	Year of Reg.	30/12/2021
Chassis No.	VBKJPC402LC072797	Colour	ORANGE
Odometer	43974 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110/60 R17	BRIDGESTONE	5
L/H Front Tyre			
R/H Rear Tyre	150/60 R17	BRIDGESTONE	5
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/09/2024	Inspection Date	25/10/2024
Survey held at	DIRT WHEEL MOTOR TRADING BLK 9004 #01-100 TAMPINES ST 93 SINGAPORE 528838		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days