



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI24100372/Rvp3m4  
(BUDGET DIRECT INSURANCE) Date: 06/12/2024  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE SINGAPORE 239924 Code: AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 2156C	Veh. Inspected	XE 6428A
Policy No.	P10911222R01	Coverage	0
Claim No.	C10032323/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	21/10/2024

### 2. Vehicle Details

Make & Model	CAMC HN1311X40E5M6	C.C	11813
Engine No.	CM6D2840060120F07631	Year of Reg.	10/05/2021
Chassis No.	LZ5N2DE54MB001157	Colour	WHITE
Odometer	218930 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	315/80R22.5	BRIDGESTONE	8
L/H Front Tyre	315/80R22.5	BRIDGESTONE	8
R/H Rear Tyre	315/80R22.5 (D)	BRIDGESTONE	8/8
L/H Rear Tyre	315/80R22.5 (D)	BRIDGESTONE	8/8

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	18/10/2024	Inspection Date	23/10/2024
Survey held at	R&S ENGINEERING WORKS PTE LTD 13, PIONEER SECTOR 1, SINGAPORE 628424		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days