



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100375/Uvp3e2
16 RAFFLES QUAY	Date:	29/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6434A	Veh. Inspected	SLA 5170L
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009266MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	21/10/2024

2. Vehicle Details

Make & Model	CITROEN C4 PICASSO (A)	C.C	1560
Engine No.	10JBHD3026328	Year of Reg.	03/03/2016
Chassis No.	VF73DBHZTFJ854111	Colour	GREY
Odometer	264711 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	DAVANTI	6
L/H Front Tyre	205/60R16	DAVANTI	6
R/H Rear Tyre	205/60R16	DAVANTI	6
L/H Rear Tyre	205/60R16	DAVANTI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2024	Inspection Date	22/10/2024
Survey held at	1 KAKI BUKIT AVE 6, #01-96 AUTOBAY @KAKI BUKIT (S) 417883 - REPAIRER: JC MOTOR CONSULTANCY		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days