

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Enderation Internationale Des Experts En Automobile				
Affiliated to Federation Internationale Des Experts En Automobile					
MS	AUTO & GENERAL	, ,	Ref:	CS/AGI24100376/Kqp3e2	
	(BUDGET DIRECT 190 CLEMENCEAU		Date:	12/11/2024	
		PING CENTRE SINGAPORE 239924	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMJ 5595K	Veh. Inspected	SNR 8446J	
	Policy No.	P10371887R04	Coverage	0	
	Claim No.	C10032362/JK	Excess	\$0.00	
	Assign From	JANICE KOH	Assign Date	22/10/2024	
2. Vehicle Details					
	Make & Model	TOYOTA NOAH (A)	C.C	1797	
	Engine No.	2ZR0E27390	Year of Reg.	27/09/2019	
	Chassis No.	ZWR800402802	Colour	METALLIC BLACK	
	Odometer	110049 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	205/55R16	MICHELIN	9	
	TOTT TOTT TYPE				
	L/H Front Tyre	205/55R16	MICHELIN	9	
		205/55R16 205/55R16	MICHELIN MICHELIN	9	
	L/H Front Tyre		+		
4.	L/H Front Tyre R/H Rear Tyre	205/55R16	MICHELIN MICHELIN	9	
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/55R16 205/55R16	MICHELIN MICHELIN of Damages	9	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/55R16 205/55R16 Description o ED DAMAGES AT THE FRONT O/S PC	MICHELIN MICHELIN of Damages	9	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	205/55R16 205/55R16 Description o ED DAMAGES AT THE FRONT O/S PC	MICHELIN MICHELIN of Damages ORTION.	9	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	205/55R16 205/55R16 Description of ED DAMAGES AT THE FRONT O/S PC	MICHELIN MICHELIN of Damages ORTION.	9	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN MAGES SEE DETAIL	205/55R16 205/55R16 Description of ED DAMAGES AT THE FRONT O/S POS. General Interpretable Control of the Cont	MICHELIN MICHELIN of Damages ORTION. formation Inspection Date	9 9	
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL	205/55R16 205/55R16 Description of ED DAMAGES AT THE FRONT O/S PC S. General Integral 21/10/2024 MASSIVE TRADING & AUTO - BLK 50	MICHELIN MICHELIN of Damages ORTION. formation Inspection Date	9 9	
THE DAM 5. 5a. A) T	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre EVEHICLE SUSTAIN MAGES SEE DETAILS Accident Date Survey held at HE INSPECTION WA	205/55R16 205/55R16 Description of ED DAMAGES AT THE FRONT O/S PC S. General Int 21/10/2024 MASSIVE TRADING & AUTO - BLK 50 SINGAPORE 569541	MICHELIN MICHELIN of Damages ORTION. formation Inspection Date 038 ANG MO KIO IN arks EJUDICE" BASIS.	9 9 22/10/2024 IDUSTRIAL PARK 2 #01-405	

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days