ASS. REC. BY: REF: A16.	
Renneth	ASSIGNMENT
From: Date:	Veh No: SNG 9261B Yr Regn: C9, 22
	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD /TP /WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No:	Truck / Trailer or
	Make: Renault Sceniz c.c 1861
of Office Optime	Colour N. P. White AC: Insured / Std / NI / NA
Insured:	Sp.Reading 205376 T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:
	CNO: <u>VF1RFA 000 6 3 217 927</u>
	Gen. Collo. Sood/ Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inarder / Jammed / Leaked / Burnt or
industrial in the second secon	Mod: NII / S/RIm / STDAR or
Online One Hill 1	Tyre Size: F: B. J 195/35R20
(Policy Condition)	R: Gren lande
Remark: The veh had commenced its repair at the time of inspection.	DIS BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUN/
	TOYO/YOKO or
Bal. or Market Value: \$ 109k	Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. Z mm R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. Z mm L/Bal. P mm
Est. Repairs:days Res.: Yes or No	D.O.A. 17/10/24 D.O.I. 23/10/2024
i. Lum Sum: 1.B.) % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / O	
Date:Person Contacted:	The U/C / Chassis framed Body Structure affected due to collision.
Date / Time Action / Instruction	& The state of the
- Lot B2	
	The state of the s
	And the state of t
R	The state of the s
11.2	
	the state of the s
and a second of the second of	
Oπίω/Timo, File Pass to? : Prell. Report	David Of h
	Days Of Repair:
Oute/Fine, File Return to?	Resurvey No. of Trip: Survey Fee:
Z) Add Fee	Transportation:
, , , , , , , , , , , , , , , , , , ,	1 _ S + RS _ SI
Danad Farification	: Interview (\$), Fix tos
Report Format :	Tach Inva (S
Lump Sum / I.B.I: (\$	Tech Invs (\$) Others
	Weekend (\$
*	70,744

OPT/MA///ERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sa

@ /optimawerkz

Date:

18-10-2024 Vehicle No: SNG9261B

Not Nothern

Third Party Insurer:
Third Party Veh No:
Date of Accident:
Estimator:
Surveyor:

AIG GU8200T

Model:

Renault Scenic

17/10/2024

Chassis:

VF1RFA00063211927

Loong

Reg.Year:

15.9.2022

	ESTIMATE			
N	O. DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	1 REAR BUMPER	1		\$1,500.00 —
	2 REAR LH BUMPER RETAINER	1	7)	cm \$500.00
3	REAR RH BUMPER RETAINER	1		ټر \$500.00 ⊀
4	REAR LH BUMPER SIDE SUPPORT BRACKET	1		R \$300.00 -
5		1		\$300.00
6		1		R ₂ \$1,200.00 —
7		1		By \$1,000.00
8		1		cm \$420.00
9	REAR REVERSE SENSOR 2	4	53cm \$425.00	\$1,700.00
10		1		cm \$450.00
11	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1		\$120.00
12		1		Ry \$900.00 -
13	REAR LH BUMPER UNDER COVER	1		mry \$300.00 -
14	REAR BUMPER CENTER UNDER COVER	1		\$450.00
15	REAR LH BUMPER LOWER BRACKET	1		B \$300.00
16	REAR RH BUMPER LOWER BRACKET	1	14	n \$280.00 X
17	REAR BUMPER CENTER INNER LOWER BRACKET	2	\$280.00	\$560.00
18	TAILLAMP LH	1		Bn \$960.00 4
19	TAILLAMP RH	1	9.4	\$960.00 7
20	REAR END PANEL OUTER	1		By \$1,800.00 -
21	REAR LH END PANEL OUTER EXTENSION	1		\$750.00
22	REAR END PANEL INNER	1		\$1,500.00
23	REAR END PANEL TRIM BOARD	1		\$680.00
24	SMART KEY ANTENNA	1		\$90.00
25	REAR BOOT	1		Ry \$4,000.00
26	REAR BOOT RENAULT LOGO	1		Ma \$300.00
27 F	REAR BOOT SCENIC EMBLEM	1	, ,	na \$200.00
8 F	REAR BOOT RENAULT EMBLEM	1	4	My \$280.00
9 B	BOOT REFLECTOR LAMP LH	1		m \$950.00
0 В	OOT REFLECTOR LAMP RH	1		\$950.00
_	EAR BOOT OUTER GARNISH	1		
	EAR BOOT WEATHERSTRIP	1	1 1 2 28	cm \$1,400.00
_	EAR BOOT LOCK	1	A Company	\$500.00
_	AR BOOT OUTER STRIP MOULDING	_		In \$250.00
	AR SPOILER	1		\$800.00
_	AR WINDSCREEN	1	0	\$1,400.0
_	AR WIPER ARM	1	54	\$1,800.0
	THE TAIL BUT CANALA	1		In \$300.0



OPT/MAMERKZ SINGAPORE

OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sg

[] /OptimaWerkz

/OptimaWerkz

Date:

18-10-2024

Vehicle No: SNG9261B

Model:

Renault Scenic

Chassis:

VF1RFA00063211927

Reg.Year:

15.9.2022

Third Party Insurer:

Third Party Veh No:

Date of Accident:

GU8200T 17/10/2024

Estimator:

Surveyor:

Loong

AIG

38 REAR WIPER BLADE	1		\$150.00 X
			\$200.00
			\$90.00
			\$90.00 (M \$1,500.00
			\$360.00
			\$400.00 7
		- A	\$340.00 7
			\$560.00 7
			\$560.00 7
			\$300.00 7
			\$300.00 x
			\$1,300.00 7
The state of the s			\$1,000.00
			\$2,200.00
A SHOW A SHOP CONTRACTOR OF THE SHOP OF TH			\$1,300.00
THE WAY THE COUNTY OF SIDE THAT	$\overline{}$		\$1,500.00
		n. (4-)-00100
		14 10	
		bu	P \$6,100.00 ?
			\$3,600.00
The second secon	$\overline{}$	A	vc \$4,850.00 ×
March Control of the	1		\$150.00
1	1		Bu \$1,050.00
	1		\$1,000.00
REAR EXHAUST TAIL PIPE	1		B ₁ \$1,200.00
REAR EXHAUST TAIL PIPE HEAT SHIELD - FRONT	1		\$360.00
REAR EXHAUST TAIL PIPE HEAT SHIELD - REAR			
REAR AXLE		1 344	\$400.00
REAR LH AXLE STUB			\$7,800.00
1.0			\$1,600.00
NY 1994 BM 19 1994 CO		Para la	\$120.00
			\$100.00
			B \$360.00
	1		\$180.00
	1		REPAIR
	1		REPAIR
	1		REPAIR
EAR RH CHASSIS		,	REPAI
AR ROOF INNER MEMBER	1		REPAI
THE REPORT OF THE PERSON OF TH	REAR BOOT OUTER OPENING SWITCH REAR LICENCE PLATE LAMP REAR BOOT INNER LOWER TRIM BOARD REAR BOOT INNER UPPER TRIM BOARD REAR LH BOOT HINGE REAR RH BOOT STRUT REAR RH BOOT STRUT REAR LH LUGGAGE SIDE TRIM REAR LH LUGGAGE SIDE TRIM CENTER GARNISH REAR RH LUGGAGE SIDE TRIM UPPER GARNISH REAR ROOF LINING REAR ROOF PANEL REAR ROOF PANEL REAR ROOF PANEL INNER MEMBER COVER REAR LH FENDER PANEL OUTER REAR LH FENDER PANEL QUARTER GLASS REAR EXHAUST TAIL PIPE REAR EXHAUST TAIL PIPE REAR EXHAUST TAIL PIPE HEAT SHIELD - FRONT REAR EXHAUST TAIL PIPE HEAT SHIELD - REAR REAR AXLE REAR LH ABS SENSOR BRACKET REAR LH BRAKE DISC DUST COVER REAR LH WHEEL RIM EAR LH OOOR PANEL EAR RH FENDER PANEL	REAR BOOT OUTER OPENING SWITCH 40 REAR LICENCE PLATE LAMP 41 REAR BOOT INNER LOWER TRIM BOARD 42 REAR BOOT INNER UPPER TRIM BOARD 43 REAR LH BOOT INNER UPPER TRIM BOARD 44 REAR RH BOOT INNER UPPER TRIM BOARD 45 REAR LH BOOT HINGE 46 REAR RH BOOT HINGE 47 REAR LH BOOT STRUT 48 REAR RH BOOT STRUT 48 REAR RH BOOT STRUT 49 REAR LH LUGGAGE SIDE TRIM 50 REAR LH LUGGAGE SIDE TRIM CENTER GARNISH 51 REAR LH LUGGAGE SIDE TRIM UPPER GARNISH 52 REAR LH LUGGAGE SIDE TRIM UPPER GARNISH 53 REAR RH LUGGAGE SIDE TRIM UPPER GARNISH 54 REAR RH LUGGAGE SIDE TRIM UPPER GARNISH 55 ROOF LINING 56 ROOF LINING 57 REAR ROOF PANEL TAILLAMP PANEL TAILLAMP PANEL LH REAR RH FENDER PANEL OUTER REAR LH FENDER PANEL QUARTER GLASS TREAR EXHAUST TAIL PIPE 10 REAR EXHAUST TAIL PIPE HEAT SHIELD - FRONT 11 REAR EXHAUST TAIL PIPE HEAT SHIELD - REAR 12 REAR LH ASS SENSOR BRACKET TREAR LH ABS SENSOR BRACKET TREAR LH BRAKE DISC DUST COVER 13 REAR LH BRAKE DISC DUST COVER 14 REAR LH BRAKE DISC DUST COVER 15 REAR LH BRAKE DISC DUST COVER 16 REAR LH BRAKE DISC DUST COVER 17 REAR LH BRAKE DISC DUST COVER 18 REAR LH BRAKE DISC DUST COVER 19 REAR LH BRAKE DISC DUST COVER 10 REAR LH BRAKE DISC DUST COVER 10 REAR LH BRAKE DISC DUST COVER 11 REAR LH BRAKE DISC DUST COVER 12 REAR LH BRAKE DISC DUST COVER 14 REAR LH CHASSIS 15 RAR RH CHASSIS 16 RR CHASSIS 17 AR ROOF INNER MEMBER	39 REAR BOOT OUTER OPENING SWITCH 40 REAR LICENCE PLATE LAMP 41 REAR BOOT INNER LOWER TRIM BOARD 42 REAR BOOT INNER LOWER TRIM BOARD 43 REAR LIH BOOT INNER UPPER TRIM BOARD 44 REAR RH BOOT INNER UPPER TRIM BOARD 45 REAR LIH BOOT INNER UPPER TRIM BOARD 46 REAR RH BOOT INNER UPPER TRIM BOARD 47 REAR RH BOOT INNER UPPER TRIM BOARD 48 REAR RH BOOT INNER UPPER TRIM BOARD 49 REAR RH BOOT INNER UPPER TRIM BOARD 40 REAR RH BOOT TRIT 41 LIND LIND LIND LIND LIND LIND LIND LIND



OPT/MA///ERKZ SINGAPORE

OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W

www.ow.sg

(7) /OptimaWerkz

/OptimaWerkz

Date:

18-10-2024

Vehicle No: SNG9261B

Model:

Renault Scenic

Chassis:

VF1RFA00063211927

Reg.Year:

15.9.2022

Third Party Insurer:

AIG

Third Party Veh No:

GU8200T 17/10/2024

Date of Accident: Estimator:

Loong

Surveyor:

SUB TOTAL	\$75,780.00		
LESS 10%	-\$7,578.00		
PARTS TOTAL	\$68,202.00		

	N	D. SPECIAL NETT	QTY	UNIT S\$	AMOU	NT S\$	
	1	REAR BUMPER CLIPS	1		Me	\$55.00	_
	2	REAR BUMPER LOWER CLIPS	1		Ma	\$50.00	<u> </u>
	3	REAR BUMPER UNDER COVER CLIPS	1		Ma	\$50.00	_
	4	REAR BOOT INNER TRIM BOARD CLIPS	1	V T	Ma	\$50.00	_
	5	REAR WINDSCREEN AND QUARTER GLASS SEALANT	1	M	405N	\$150.00	
	6	REAR WINDSCREEN AND QUARTER GLASS PRIMER	1	M		\$100.00	
	7	REAR WINDSCREEN MOULDING	1			\$150.00	
1	8	REAR RECORDING CAMERA ON REAR WINDSCREEN	1	*		\$500.00	2
L	9	REAR WINDSCREEN SOLAR FILM	1		Me	\$400.00	200ga
L	10	REAR BOOT OUTER GARNISH CLIP	1	-	NE	\$50.00	1.5
L	11	REAR END PANEL OUTER & INNER SEALANT	1			\$150.00	
L	12	REAR FENDER PANEL SEALANT	1		Nen	\$100.00	
L	13	REAR LICENCE PLATE NUMBER WITH FRAME	1		nd	\$55.00	-
L	14	TAILLAMP GUIDE CLIPS	1			\$50.00	_
	15	REAR REVERSE SENSOR MOUNTING BRACKET SET	1			\$200.00	_
_ :	16 I	REAR EXHAUST TAIL PIPE MOUNTING AND GASKET SET	1		+	\$50.00	_
1	17 F	REAR SPOILER CLIPS	1			\$50.00	100
1	.8 R	OOF LINING CLIPS	1		100	\$50.00 \$ \$50.00	_
1	9 R	EAR ROOF PANEL SEALANT	1		+		⊣ _
2	O R	EAR WINDSCREEN "PRIVATE HIRE" DECAL FROM LTA	1		-	\$100.0	
	\neg	DEGRETHOWEIA	-		N	c \$80.0	0 4050
		· .					ta contra
				S/N TOTAL		\$2,440.0	00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

20001 \$2,800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL OUTER & INNER, REAR LH & RH FENDER, REAR LH DOOR, REAR BOOT OUTER GARNISH, REAR LH CHASSIS, TAILLAMP PANEL LH, REAR END PANEL OUTER EXTENSION, REAR ROOF INNER MEMBER, REAR BODY DRIP PANEL \$3,500.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN AND QUARTER GLASS TO **ENABLE BODYWORK REPAIR**

\$180.00

Head office

6 Kung Chong Road Singapore 169143 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112 Branch

9A Serangoon North Ave 5 Singapore 554500 Tel: (+85) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims) Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



OPTIMA WERKZ PTE LTD Co. Reg. No. 201212455W www.ow.sg f) /optimaWerkz

@ /optimawerkz

Date:

18-10-2024

Vehicle No: SNG9261B

Model:

Renault Scenic

Chassis:

VF1RFA00063211927

Reg. Year:

15.9.2022

Third Party Insurer:

Third Party Veh No:

Date of Accident:

Estimator:

AIG

GU8200T 17/10/2024

601

601

\$120.00

\$100.00

\$200.00 7

\$120.00 201

\$650.00 1201

\$100.00 X

\$400.00 ?

\$150.00 601

\$170.00 601

\$450.00 7

\$250.00

Loong

Surveyor:

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANSIM &

ETC. BACK TO ORIGINAL OPERATIONS

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

TO TUFF KOTE & UNDERSEAL MATERIALS.

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

TO CHECK WIRING & ELECTRICAL SYSTEM.

TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS, LININGS, COVER, CUSHION SEAT, GARNISH AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR

TO R&R TYRE AND RIM

TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR

TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT

TO REMOVE AND REFIT REAR EXHAUST PIPE TO ENABLE BODYWORK REPAIR

MOUNT WORKBENCH - TO REALIGNMENT REAR CHASSIS AND REPAIR ACCIDENT AREAS

TOTAL

\$79,832.00

\$9,190.00

LKK Auto Consultants hence notify the Repairer of the following:

LABOUR TOTAL

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Head office 6 Kung Chong Road Singapore 169143 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500 Tel: (+85) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims) Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

SA1H24AIM002 / AMK Autopoint Pte Ltd ENTRY DATE & TIME: 18/10/2024 11:51 (SGT) SUBMITTED BY: Joelle Tan VERSION: 1 (18/10/2024 11:51 (SGT))

© SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

pointy.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 18/10/2024 11:51 (SGT) Reported by **Actual Driver** Date of Accident 17/10/2024 13:45 (SGT) Exact Location of Accident Ang Mo Kio Ave 1, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNG9261B

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner VINCAR PTE LTD Company Reg No 200312900K **Email Address** leasingoperation@vincar.com.sg Mobile Phone No (Phone) +65-84884081 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Renault Model Scenic Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private hire Transmission Auto CC 1461 Vehicle Fuel First Regisration Date Chassis no Effective Date/Time of Ownership

INSURANCE COMPANY

Name of Insurance Company Income Insurance Limited Policy Number / Cover Note Number 5124588142-02

DRIVER

feet the city of here was a sold as in 1976

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknow ledge, agree and consent that

- (a) My insurer, my w crkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel 10elle Tan Tan

AMIC AUTOPOINT PL

A = SNG 9261B B = Gugzoot





2 of 3

Report No. T/20241017/2079

Police Station Of Origin: Punggol N.P.C 151 Punggol Central SINGAPORE 828727 Tel No: 1800-6049999

CONTINUATION OF REPORT

Name	SOH LAI SENG	aced Medial	ID No).	S0164632Z
Related Vehic	cle GU8200T (Motor van)	. 6	Conta	act No.	NIL
Hospital/Clinic	W.		Class Drivin Licen Expir	g ce &	Class: NIL Date of Expiry: NIL
Date Treatmen		Date Disch		NIL	
No. of Days gra Drive r	nted Medical Leave NIL	Degree of		NIL	
The second secon					
Name	NG CHENG SAN		ID No		S1441224G
Related Vehicle	SNG9261B (Motor car)	Se april o se les persones de la company	Conta	ct No.	92331311
ospital/Clinic	TRINITY MEDICAL (PUNGGOL)		Class of Driving Licence &		Class: 3 Date of Expiry: NIL
te Treatment	17/10/2024	Data Disat	Expiry		
of Days grante	d Medical Leave 03	Date Disch	arge		/2024
	20070 03	Degree of	100	Slight	-

Brief Details.

On the 17th October 2024 at about 1.40 pm, I was driving my vehicle (SNG9261B) along Ang Mo Kio Avenue 1 towards Bishan. As I was approaching the junction of Ang Mo Kio Avenue 10, the traffic light was red in colour and I had stopped my vehicle on the 2nd or 3rd lane of the 4-lane road. Suddenly, there was another vehicle (GU8200T) which collided into the rear of my vehicle. The impact was very hard and was no passenger in my vehicle at that point of time.

I had alighted from my vehicle together with the driver of the other vehicle to exchange details. Due to the accident, I felt pain at the back of my neck and lower back area and I also felt giddiness. I had gone to the Trinity Medical clinic at Apt Blk 273C Punggol Place #01-874 S823273 to seek treatment for my injuries and I was given 3 days medical leave. There is a rear camera installed in my vehicle but I am unable to retrieve the footage and it was also badly damaged.

> Back to OneMotoring

Vehicle Owner Particulars	Company
Owner ID Type:	Company 900K
Owner ID:	YUUN
Vehicle Details	SNG9261B
Vehicle No.:	Yes
Vehicle to be Exported:	17 Oct 2024
Intended Deregistration Date:	RENAULT
Vehicle Make:	GRAND SCENIC IV 1.5 DCI AT EU6
Vehicle Model:	White
Primary Colour:	2019
Manufacturing Year:	K9KF649D060274
Engine No.:	VF1RFA00063211927
Chassis No.:	81.0 kW (108 bhp)
Maximum Power Output:	\$25,525.00
Open Market Value:	15 Sep 2022
Original Registration Date:	15 Sep 2022
First Registration Date:	0
Transfer Count:	\$12,735.00
Actual ARF Paid:	Ψ12,7 03.00°
Intended PARF Rebate Details	Yes
PARF Eligibility:	14 Sep 2032
PARF Eligibility Expiry Date:	\$9,551.00
PARF Rebate Amount:	\$9,551.00
Intended COE Rebate Details	44 Cam 2022
COE Expiry Date:	14 Sep 2032
	A - Car-Details at OneMotoring
COE Category:	10
COE Period(Years):	\$68,001.00
QP Paid:	\$53,787.00
COE Rebate Amount:	\$63,338.00
Total Rebate Amount:	
	1.005 (

Message
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.
The information contained herein is correct as at 17 Oct 2024