

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate: \_\_\_\_\_

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: \_\_\_\_\_

at W/O \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Vehicle: \_\_\_\_\_

(Policy Condition)

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKX298B Yr Regn: 2015, Dec.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz A180 C.D. 1595

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 160255 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WDD1760422J406097

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 21/10/24

Survey held at Premium Carz

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP A16

COE Expiry

Estimate given during : Yes ( )

1st Survey : No ( )

MV: 281K

PV: 16.9K

Nett: 11.1K

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Inve (\$ \_\_\_\_\_)

Photos

Others

Report Format: \_\_\_\_\_

Engine No / L.P. / C.D.