

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	(Not Notified) Edit Reg		24 Oct 2024 00:00 Edit Adj Rpt			Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS[Created by adjuster]

Insured:

Main Claimant:

Vehicle Reg. No.:

Claim Type:

Vehicle Reg. No. (Insured):

Reparer:

Handling Insurer:

Adjuster:

-

SHD6781Z

TP

SGZ4011Y

ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300

ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199 ... [Handled by **Foo Ai Ngoh**]

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by **CHEN TSUE YEE**] ... **[Final Rpt due 05/11/2024]**

Date of Loss :

Policy/Cover Note No. :

Policy No. (Claimant):

Excess:

21/10/2024 00:00 - 00:59

ASSOCIATED MAIL RECEIVEDView AllCompose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKSView AllSearch TasksCreate New TaskComplete

Due DatePriorityTypeTask GroupSubjectHandlerAssigned ByCompleted OnCreated OnDone?

No results.

ALL ASSOCIATED FILE NOTESCreate New

No. Status TypeViewer/Assigned ToNoteCreated OnCreated By1st Read By

No results.

