ASSIGNMENT

From:	Date:	Veh No: SHD6781Z Yr Regn: 08 A/pr 201
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV		Truck / Trailer or
	No:	Make: MERCEDES BENZ E220 c.c 2143
2 2 2 2		Colour White A/C: Insured / Std / NI / NA
	3	Sp.Reading 1093482 T/Radio: Insured / Std / NI / NA
1		Eng/No:
		C/No: WDD2120012B308922*
		Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured:	Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)		Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:		Modi: Nil / S/Rim / STD A/Rim or
		Tyre Size: F: 225/55R16
(Policy Condition)		R:
Remark: The veh had commenced its N/S O/S		BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at	the time of inspection.	TOYO / YOKO or DURATURN
Bal. or Market Valu		<u>Front</u> <u>Rear</u>
IDAC Accident Rpo	ort: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs:	days Res.: Yes or No	D.O.A. 21/10/24 D.O.I. 23/10/24
Lum Sum:	% 3 Val.: Yes or No	Survey held at Confortdelgro
CA / REV / F	REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Dele	Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collisio
	Action / Instruction	- The old / chassis hame / Body chaster
Date / Time	Action / Instruction	
	Steve confirmed lump sum \$18	350.00. 2 days.
	(red, \$2851.25, 60%)	
	,	
	-	
*		
	II	Days Of Repair: 2
Date/Time, File Pass		
1)	: Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
Date/Time, File Retu	Add F	
2)	, and i	: Interview (\$) Photos
Barrellaune	· iz	: Tech. Invs (\$) Others
Reperformal: Lump Sum / LB J: CB		: Weellend (\$)
French Traces	tele de « ;	70741