

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD6801A

DATE 21.10.2024

MAKE REG 08.04.2016

CHIANG/LONPAC

MODEL MERC E6

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER / <i>OD</i>			\$1,510.00
1	REAR BUMPER REINFORCEMENT <i>1</i>			\$1,150.00
2	REAR BUMPER RETAINER MOUNTING LH/RH <i>1</i>		\$115.00	\$230.00
2	REAR BUMPER BRACKET LH/RH <i>1</i>		\$135.00	\$270.00
1	REAR BUMPER LOWER COVER <i>cut</i>			\$325.00
1	REAR BUMPER TOWING COVER <i>BR</i>			\$175.00
1	REAR END PANEL <i>X</i>			\$1,380.00
1	REAR PANEL INNER GRANISH <i>X</i>			\$124.80
1	BOOT LID <i>X R</i>			\$2,470.00
1	BOOT LID LOCK <i>X</i>			\$275.00
1	BOOT LID EMBLEM E220 <i>1pc</i>			\$84.30
	SUB TOTAL			\$7,994.10
	LESS 20%			\$1,598.82
				\$6,395.28
1	REAR BUMPER SENSOR <i>1</i>			\$388.00
				\$388.00
	Labour Charge			
	Panel Beating <i>400</i>			\$1,400.00 <i>800</i>
	Spray Painting Charge <i>450</i>			\$800.00 <i>900</i>
	Remove/Refix Reverse Sensor			\$90.00 <i>20</i>
	Tuff Coating			\$60.00 <i>20</i>
	TOTAL LABOUR			\$2,350.00
	ESTIMATE TOTAL			\$9,133.28
<i>Store (LKK)</i> <i>23/10/24, 11.00am</i> <i>W L</i> <i>L/S</i> <i>by AL by</i> <i>3 days</i>				
This is an initial estimate based on a visual inspection. It will be prepared after the vehicle is surveyed by a r				tum will any.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	22/10/2024 08:41 (SGT)
Reported by	Actual Driver
Date of Accident	21/10/2024 15:10 (SGT)
Exact Location of Accident	Simei Ave, Singapore
Additional Location Information	TOWARDS PIE / TUAS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6801A
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-96698129
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E220
Variant	BLUETEC
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	2143
Vehicle Fuel	Diesel
First Registration Date	-
Chassis no	WDD2120012B316970
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-24101861MFCT

DRIVER

Name of Driver ENG BOON HUA
 NRIC No SXXXX305D
 Date Of Birth 09/02/1963
 Occupation Outdoor
 Driving Pass Date 30/05/1984
 Driving License Pass Class 3
 Driving License Validity Valid
 Driving experience 40 YEARS AND 5 MONTHS
 Gender Male
 Mobile Number (Phone) +65-96698129
 Alt. Phone Number -
 Email Address fleetsafety@cdgtaxi.com.sg
 Address BLK 299B COMPASSVALE STREET # 15 - 104
 Address complement -
 Postcode 542229
 Is the driver the policyholder? No
 If No, Relationship of the Driver with the Insured Hirer
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? No
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
 Translator's name -
 Translator's ID -
 Translator's phone number -
 Translator's email -
 Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON 21.10.2024 AT ABOUT 1510HRS, VEHICLE A SHD6801A WAS ALONG SIMEI AVE . VEHICLE A WAS STATIONARY ON THE MOST LEFT LANE IN QUEUE TOWARDS PIE / TUAS. VEHICLE B GBE1839R THEN REAR ENDED STATIONARY VEHICLE A. UPON IMPACT I HURT MY NECK AND FELT NAUSEOUS. SCENE PHOTOS TAKEN . PARTICULARS EXCHANGED.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Reasons for not uploading a video of the accident FILE IS NOT SUITABLE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE1839R
Vehicle Manufacturer	Nissan
Vehicle Model	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	LI YANCHENG
Work Permit No	GXXXX257N
Contact Number	(Phone) +65-98554824
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	FRONT
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ENG BOON HUA
Gender	Male
Phone No	(Phone) +65-96698129
Address	299B COMPASSVALE STREET # 15 - 104
Address Complement	-
Post Code	542229
Approximate Age Years Old	61
Injuries Sustained	NECK PAIN AND FELT NAUSEOUS
Injured person in which vehicle?	SHD6801A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN**IMPORTANT NOTICE**

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (Collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time



Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

21.10.2024.

1730HRS

Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident

ON 21.10.2024 AT ABOUT 1510HRS, VEHICLE A SHD6801A WAS ALONG SIMEI AVE. VEHICLE A WAS STATIONARY ON THE MOST LEFT LANE IN QUEUE TOWARDS PIE / TUAS. VEHICLE B GBE1839R THEN REAR ENDED STATIONARY VEHICLE A. UPON IMPACT I HURT MY NECK AND FELT NAUSEOUS. SCENE PHOTOS TAKEN. PARTICULARS EXCHANGED.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time
21.10.2024. 1730HRS

Witnessed by Reporting Centre Personnel

