



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100390/Avh3e2
75 BRAS BASAH ROAD	Date:	11/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 4873B	Veh. Inspected	GBK 6028A
Policy No.	-	Coverage	0
Claim No.	MT/1300742-002	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	23/10/2024

### 2. Vehicle Details

Make & Model	NISSAN NV200	C.C	1598
Engine No.	HR16166158D	Year of Reg.	16/09/2020
Chassis No.	JN1YAAM20Z0001055	Colour	BLACK
Odometer	204298 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/70 R14C	DUNLOP	6
L/H Front Tyre	175/70 R14C	DUNLOP	6
R/H Rear Tyre	175/70 R14C	DUNLOP	6
L/H Rear Tyre	175/70 R14C	DUNLOP	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	18/10/2024	Inspection Date	23/10/2024 (12:31)
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days