



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI24060229/Aqh3

Date: 30/09/2024

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3893U	Veh. Inspected	SLZ 3706Z
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005546MFCT	Excess	\$0.00
Assign From	JOANNE TAN	Assign Date	25/06/2024

2. Vehicle Details

Make & Model	KIA FORTE K3 1.6A	C.C	1591
Engine No.	G4FGJH697400	Year of Reg.	30/04/2018
Chassis No.	KNAFJ411MJ5767313	Colour	RED
Odometer	59103 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	MICHELIN	6
L/H Front Tyre	195/65R15	MICHELIN	6
R/H Rear Tyre	195/65R15	MICHELIN	6
L/H Rear Tyre	195/65R15	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/06/2024	Inspection Date	25/06/2024
Survey held at	HD PERFECT AUTOWORK PTE LTD - 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days