



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100401/Enp3m4
(BUDGET DIRECT INSURANCE)	Date:	04/12/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 557L	Veh. Inspected	SLP 5651L
Policy No.	-	Coverage	0
Claim No.	C10032351/KC	Excess	\$0.00
Assign From	KIAN CHUAN	Assign Date	23/10/2024

2. Vehicle Details

Make & Model	PORSCHE 718 BOXSTER	C.C	1988
Engine No.	DPP013599	Year of Reg.	09/06/2017
Chassis No.	WP0ZZZ98ZHS214135	Colour	BLACK
Odometer	95699 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/40ZR19	YOKOHAMA	5
L/H Front Tyre	235/40ZR19	YOKOHAMA	5
R/H Rear Tyre	265/40ZR19	YOKOHAMA	5
L/H Rear Tyre	265/40ZR19	YOKOHAMA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/10/2024	Inspection Date	19/11/2024
Survey held at	WIN AUTOMOTIVE SERVICES PTE LTD - 60 JLN LAM HUAT, #04-53 CARROS CENTRE, SINGAPORE 737869		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days