

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodland
FAX Number
Estimator Te
Accident Rep

Date Generated
User ID

TP
AIG
78

Section A - Accident Details


Registration Number	SHF253K
Case Reference Number	TAX/06/24/2010
Registration Date	14/12/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HWEE MING SIANG (WEI MINXIAN)
Type of Accident	Head to Rear
Accident Date and Time	3/6/2024 6:25 PM
Accident Reported Date and Time	4/6/2024 4:30 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121544
Special Instruction to ARC, if any	TP/ REAR PORTION/TOS/AIG - LKK
Prepared Date and Time	11/6/2024 10:52 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$1,478.00	\$0.00
Total Spare Part Cost	\$3,967.28	\$0.00
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$6,790.28	\$0.00
Lump Sum Total	\$6,800.00	\$0.00
Number of Repair Days	7.0	
Prepared / Adjusted By	ARC Manager Team	2 days Tonghai 92977243
ARC / Surveyor Sign Off Date	11/06/2024 11:11 AM	11/6/24 11:30pm Tonghai
Signature		
Remarks		1/5 Resurvey after repair - Tonghai 11/6/24

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
GO Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Generate

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, If applicable
TO REPAIR REAR PORTION	\$845.00	200
Total Labour	\$845.00	200

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
TO RESPRAY BUMPER BEAM	\$220.00	x un
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR PANEL	\$220.00	x 7
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	x 7
TO RESPRAY FILLER RR BUMPER LH	\$220.00	x 7
TO RESPRAY FILLER RR BUMPER RH	\$220.00	x 7
Total Spray Painting & Panel Beating	\$1,478.00	200

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicable
TO WASH AND VACUUM	\$60.00	x 7
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	y 7
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	x 7
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	30
TO REPLACE SUNDRY PARTS	\$100.00	x un
Total Other Costs	\$500.00	30

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace Ry	
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace x 7	
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace x 7	
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace x 7	
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace y 7	
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace y 7	
		5219147030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace x 7	
		5259968030	STOPPLER, RR BUMPER, RH & LH	2.00	\$4.80	25.00	\$7.20	Replace x 7	
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace x 7	
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace x 7	
		5259147050	SEAL, RR BUMPER, RH	1.00	\$95.50	25.00	\$71.63	Replace y 7	
		5259247040	SEAL, RR BUMPER, LH	1.00	\$95.50	25.00	\$71.63	Replace y 7	
		5216116010	CLIPS PILCE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace x 7	
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace ad-	
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace x 7	
		5256647900	FILLER, RR BUMPER, LH	1.00	\$168.60	25.00	\$126.45	Replace y 7	
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.52	Replace x 7	
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace x 7	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		8999730100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	25.00	\$58.50	Replace ☒	
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	25.00	\$366.75	Replace ☒	
		8156147151	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$489.00	25.00	\$366.75	Replace ☒	
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	25.00	\$408.30	Replace ☒	
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$544.40	25.00	\$408.30	Replace ☒	
		5839847050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace ☒	
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace ☒	
		6625947010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace ☒	
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$992.30	25.00	\$744.22	Replace ☒	
		7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace ☒	
		7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace ☒	
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace ☒	
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace ☒	
		5830747090	END PANEL SUB-ASSY, BODY LOWER BACK	1.00	\$707.10	25.00	\$530.33	Replace ☒	
Total					\$7,171.20		\$5,489.43	Replace ☒	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ct
Total									

467.63
20% - 374.10

200
200
30

804.10 ≈ 65\$800
* 2 days