

ASS. REC. BY:

REF:

LPL

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 En not ready
4/7 11pm @ 2500h. Calm

Veh No:

Jmy 78336r Regn: 09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS X-Trai

c.c

Wagon 1997

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

99231

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNITANT 328 0010185

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Armstrong

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/6/24

D.O.I.

25/6/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not Authorized
11 Day @ 2500p
Resurvey After Paint
3 days

THIAM HENG HUAT PTE LTD
176 SIN MING DR #05-14
SINGAPORE 575721

VEH NO: SMY 7833G
MODEL: NISSAN X-TRAIL

DATE : 28/06/2024

1PC REAR BUMPER ASSY	Bu \$	693.10	✓
1PC REAR BUMPER CENTRE GRILL	\$ In	56.00	X
1SET REAR BUMPER CLIPS	nn	50.00	✓
2PCS REAR SIDE RETAINERS	nn	77.80	X
1PC REAR BUMPER REINFORCEMENT	R	576.20	✓
1PCS REAR BUMPER REINFORCEMENT BRACKETS @165	nn	390.00	✓
1PC REAR BUMPER CENTRE CHROME 420	cm	560.00	✓
2PCS REAR BUMPER REFLECTORS	In	133.20	X
1PC REAR END PANEL	R	447.50	X
1PC REAR END PANEL GARNISH	In	85.00	X
1PC REAR END PANEL LOWER PLATE	In	111.30	X
1PC REAR EXHAUST PIPE	R	1,244.30	X
1PC TAIL GATE ASSY	R	4,380.00	X
1PC TAIL GATE LOCK	R	613.70	X
1PC TAIL GATE LATCH	\$ R	51.50	X
1PC TAIL GATE WEATHER STRIP	\$ In	140.80	X
1PC TAIL GATE LOGO	nn	64.90	✓
1PC TAIL GATE EMBLEM "X-TRAIL"	nn	110.80	✓
1PC TAIL GATE GLASS MOULDING	nn	72.70	X
		\$ 9,858.80	
		\$ 985.88	
		\$ 8,872.92	

Less 10% ✓
288

S/N			
1SET REVERSE SENSOR (4 EYES)	add short	\$ 480.00	200.00
PANEL SEALANT	nn	\$ 80.00	X
WINDSCREEN GLASS SEALANT	nn	\$ 80.00	X

LABOUR			
PANEL BEATING		\$ 1,000.00	500
SPRAY PAINTING		\$ 1,000.00	600
RUST PROOFING	nn	\$ 100.00	X

Grand total

\$ 11,612.92

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: