

REF: CS/LAW24100408/Uqp3 (SLU 2336R)

Special Instruction:

ASSIGNMENT (Office)

From (Person): IGENE of AXALT Date/Time: 21/10/2024

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

L/SUM: 14,200

Third Parties:

Claimant:

Surveyor: MC-COY APPRAISER PTE LTD

Workshop: BLUWEL AUTOMOTIVE  
SERVICE PL

OD TP Re-inspection Evaluation

To Inspect Vehicle No: SLU 2336R

Insured: SMD 1053R

at Workshop m/s BLUWEL AUTOMOTIVE SERVICE PL Tel:

of 1 KAKI BUKIT AVENUE 6, #01-55, AUTOBAY, S(417883)

Policy No: \_\_\_\_\_ Claim No: ALL.B1.2401392.ig

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 03/04/2024  
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red \$\_\_\_\_/\_\_\_\_%; Original \_\_\_\_ days)

Date/Time: 06/11/24 Submit ~~Final Fig~~ LS \$9600, 12 days (Red \$ 4600 / 32 %; Original 15 days)

[illegible]

---

**Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)**

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Basic &amp; Add

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

1) Date/Time 06/11/24 File Pass to Typist

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_