

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Est: \_\_\_\_\_  
 OD / TP RES / OD RES / EVA / INV / MV  
 To in Vehicle No: \_\_\_\_\_  
 at Work \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Vehicle: \_\_\_\_\_  
 (Policy Condition)

Remarks: Vehicle had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBK1145C Yr Regn: 2020, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace DX C.D. 2754

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 228899 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: GDH 2012009574

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 195R15C

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ariva

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.A. 24/10/24

Survey held at N51

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chinn

COE Expiry: \_\_\_\_\_

Estimate given during: Yes ✓

1st Survey: No ( )

MV: 77K

PV: 12K

Nett: 65K

084M

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Form ref:

Report Form ref: