

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

Remark: Driver had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBL8377Z

Yr Regn: 2022 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Townace

CO 1496

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 58935

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: S403M0011635

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 165/80R14

R: 165/80R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

D.O.I. 22/10/24

Survey held at In Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Chian

COE Expiry: _____

Estimate given during: Yes (✓)

1st Survey: No ()

MV: G41C

PV: 297K

Nett: 34.3K

731C

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee: _____

Transportation: _____

3 - R.S. \$1

Photos

Others

E. report Formist: _____

E. report Formist: _____

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 21.10.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : GBL8377Z
MODEL : TOYOTA TOWN ACE
DATE OF ACCIDENT : 11.10.2024
TIME OF ACCIDENT : 15:09 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delnd</i>	1	\$ -	\$ -
2	REAR BUMPER TOWING COVER <i>Delnd</i>	1	\$ -	\$ -
3	REAR BUMPER SIDE RETAINER <i>Delnd</i>	2	\$ -	\$ -
4	REAR BUMPER SENSOR <i>Delnd</i>	2	\$ -	\$ -
5	REAR BUMPER SENSOR WIREHARNESS <i>Delnd</i>	1	\$ -	\$ -
6	TAIL LAMP <i>Delnd</i>	2	\$ -	\$ -
7	TAILGATE <i>Delnd</i>	1	\$ -	\$ -
8	TAILGATE OUTER GARNISH <i>Delnd</i>	1	\$ -	\$ -
9	TAILGATE INNER LOCK <i>Delnd</i>	1	\$ -	\$ -
10	TAILGATE INNER LOCK MOTOR <i>Delnd</i>	1	\$ -	\$ -
11	TAILGATE INNER BOARD <i>Delnd</i>	1	\$ -	\$ -
12	TAILGATE LOWER LOCK <i>Delnd</i>	1	\$ -	\$ -
13	TAILGATE STOPPER (UPPER) <i>Delnd</i>	2	\$ -	\$ -
14	TAILGATE STOPPER (LOWER) <i>Delnd</i>	2	\$ -	\$ -
15	TAILGATE LOGO <i>Delnd</i>	1	\$ -	\$ -
16	TAILGATE WEATHERSTRIP <i>Delnd</i>	1	\$ -	\$ -
17	TAILGATE WEATHERSTRIP PROTECTOR <i>Delnd</i>	1	\$ -	\$ -
18	TAILGATE OUTER KEY LOCK <i>Delnd</i>	1	\$ -	\$ -
19	TAILGATE STICKER "GL" <i>Delnd</i>	1	\$ -	\$ -
20	TAILGATE WINDSCREEN MOULDING <i>Delnd</i>	1	\$ -	\$ -
21	REAR END PANEL (INNER) <i>Delnd</i>	1	\$ -	\$ -
22	REAR END PANEL (OUTER) <i>Delnd</i>	1	\$ -	\$ -

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBL8377Z
 MODEL : TOYOTA TOWN ACE
 DATE OF ACCIDENT : 11.10.2024
 TIME OF ACCIDENT : 15:09 HOURS

23	REAR FLOOR PANEL <i>Repair</i>	1	\$ -	\$ -
24	REAR FLOOR MAT <i>new</i>	1		
25	REAR SPARE TYRE HOLDER BOLT <i>2nd</i>	1	\$ -	\$ -
26	REAR SPARE TYRE HOLDER SUPPORT BRACKET <i>2nd</i>	2	\$ -	\$ -
27	REAR SPARE TYRE HOLDER BRACKET <i>2nd</i>	1	\$ -	\$ -
28	REAR EXHAUST <i>2nd</i>	1	\$ -	\$ -
29	REAR EXHAUST MOUNTING <i>1st</i>	1	\$ -	\$ -

TOTAL PRICE \$ -
 LESS 25% \$ -
 SUB TOTAL PRICE \$ -

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	TAILGATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAIL GATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00
4	TAIL GATE CHINESE WORD <i>new</i>	1	\$ 30.00	\$ 30.00
5	TAIL GATE '70KM/H' STICKER <i>new</i>	1	\$ 30.00	\$ 30.00
6	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
7	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
8	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 350.00	\$ 350.00

TOTAL \$ 780.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>700</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>600</i>
3	TUFF COAT	\$ 350.00	<i>60</i>
4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>40</i>
5	REMOVE AND REFIX REVERSE SENSOR	\$ 80.00	<i>30</i>
6	REMOVE AND REFIX REVERSE CAMERA	\$ 120.00	<i>50</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : GBL8377Z
MODEL : TOYOTA TOWN ACE
DATE OF ACCIDENT : 11.10.2024
TIME OF ACCIDENT : 15:09 HOURS

7	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	+
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 150.00	+
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	+

TOTAL \$ 5,380.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 780.00
TOTAL LABOUR COST : \$ 5,380.00
TOTAL REPAIR COST : \$ 6,160.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES. LKK Auto Consultants hence notify

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
2/8 22/10/24
J B Ayo