## ASSIGNMENT

Data	Veh No: SNP5580J Yr Regn: 26 Fe/b 2024
From: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
	Make: HYUNDAI SX2 KONA c.c 1580
To Inspect Vehicle No:	Colour White A/C: Insured / Std / NI / NA
at Workshop m/s	Sp.Reading 53106 T/Radio: Insured / Std / NI / NA
of SNF 5880X	Eng/No:
insured.	C/No: KMHHB811VRU037070
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No. SNM24D206007	Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	005/05040
	X 1,10 0.120.
(Policy Condition)	4
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or TRIANGLE
repair at the time of inspection.	Dear
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs:days Res.: Yes or No	D.O.A. <u>25/10/24</u> D.O.I. <u>28/10/24</u>
Lum Sum: % 3 Val.: Yes or No	Survey held at My Car Consultant
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OU	T Front RH
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction  MV - \$160k	
IVIV - \$TOUK	
13/11/24 LS \$3800 confirmed by email (red	d 5162.80, 57%)
10/11/24 == \$\frac{1}{2} 2.51.61.11.12.12.13.13.13.13.13.13.13.13.13.13.13.13.13.	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 4
- Final Papert	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add F	ee: : Site Insp (\$)_s+Rssi
in j	: Interview (\$ ) Photos
	i interior
Renatiforniai :	: Tech. Invs (\$ ) Others
RepetFormal: Lump Sum / LBJ: (% )	NEW COLUMN