

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at W/O km/s

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: There had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLU599911 Yr Regn: 2017, DecType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra C.D. 1591Colour: Gold A/C: Insured / Std / NI / NASp. Reading: 170821 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH D84CMJU 590490Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16
R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 28/10/24Survey held at JECDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP INC

COE Expiry: _____

Estimate given during: Yes ()

1st Survey: No (✓)

MV:

PV:

Nett:

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: _____

1) _____

☐: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐: Site Insp (\$ _____)☐: Interview (\$ _____)☐: Tech. Insp (\$ _____)

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

Report Format:

A. Report Form / B. P. Form

287H