

(08/11/13) Wef

ASS. REC. BY:

REF: CS/AWA 24100485/Rup3

927C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SL2 8750Lat Workshop m/s mo nelsonof 3LN B&WInsured: XE 4155A AWPPolicy No. BVF2SB0002812301Claims No. CSG24VF2PA00013/HLF

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 48k

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SL2 8750LYr Regn: 2017 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SSANKYONH STUIC 2000 c.c. 1998

Colour

GRNAC: Insured / Std / NI / NA

Sp. Reading

121762T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KPTV0BITSHP122588Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/70R16C

R:

4 9

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

18/10/24

D.O.I.

28/10/24

Survey held at

JLN B&WDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR Limit - 15K

25/11/24 Rasul confirmed LS \$3450 (red 9690.27, 73%)

Date/Time, File Pass to?

☐
☐

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐
☐
☐
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) B + RG \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Motorway Car Care Centre Pte Ltd

1094 Lower Delta Road Motorway Building Singapore 169205

Tel: 6468-2200 fax: 6278-5535

GST:200000606-K RCB NO: 200000606-K

ALLIED WORLD ASSURANCE COMPANY LTD

60 ANSON ROAD #08-00

SINGAPORE 079914

ATTN: MOTOR CLAIM DEPARTMENT

Your Ref No : SLZ8750L

Claim Type : Third Party

Accident Date : 18/10/2024

TP Veh Reg No : XE4155A

Estimate No. : WQT0002183

Date : 26-Oct-24

Policy No : SD24V04867 /VPZ /R07

Veh Reg No : SLZ8750L

Make / Model SSANGYONG STAVIC
2.0D AUTO 2WD 9 SEATER

Chassis No : KPTV0B1TSHP122598

Engine No : 67196022688010

Reg.Date : 16/11/2017

Estimate Repair Cost to Vehicle No :SLZ8750L

DESCRIPTION	QTY	LIST PRICE	AMOUNT
		\$\$	\$\$
1 PNL ASSY-TAILGATE <i>repa</i> ✓	1	\$ 2,556.13	\$ 2,556.13
2 PNL ASSY-TAILGATE 'SSANGYONG' EMBLEM <i>re</i> ✓	1	\$ 51.15	\$ 51.15
3 PNL ASSY-TAILGATE 'STAVIC' EMBLEM <i>X</i>	1	\$ 56.43	\$ 56.43
4 W/STRIP-TAIL GATE OPENING <i>X</i>	1	\$ 200.58	\$ 200.58
5 COMBI LAMP ASSY-RR QTR LH / RH <i>sa? 4.9?</i>	1 <i>X</i>	\$ 372.38	\$ 744.75
6 COMBI LAMP ASSY-T/GATE RR LH / RH <i>sa? 4.9?</i>	1 <i>X</i>	\$ 370.13	\$ 740.25
7 FASCIA-RR BUMPER <i>de</i> ✓	1	\$ 1,936.43	\$ 1,936.43
8 LAMP ASSY-REFLEX REFLECTOR LH / RH <i>X</i>	2	\$ 53.83	\$ 107.65
9 BRKT ASSY-SIDE RR BUMPER LH / RH <i>X</i>	1	\$ 71.60	\$ 71.60
10 BRKT ASSY-SIDE R/BPR INR LH / RH <i>X</i>	1	\$ 56.73	\$ 56.73
11 ABSORBER-ENERGY RR BUMPER <i>?</i>	1	\$ 443.81	\$ 443.81
		LIST TOTAL S\$: \$	9,466.97
		10.00% DISCOUNT S\$: \$	946.70
		\$	8,520.27

SPECIAL NETTS	QTY	UNIT PRICE	AMOUNT
		\$\$	\$\$
1 TAILGATE GLASS SEALANT <i>X</i>	1	\$ 100.00	\$ 100.00
2 TAILGATE INNER TRIM BOARD CLIPS <i>X</i>	1	\$ 80.00	\$ 80.00
3 REAR BUMPER CLIPS <i>re</i> ✓	1	\$ 80.00	\$ 40.00
5 REVERSE SENSOR <i>?</i>	1	\$ 350.00	\$ 250.00
		\$	610.00

LABOUR CHARGE (LABOUR \$400 // SPRAY PAINT \$450)

\$\$

- | | | | |
|---|---|----|-------------------------|
| 1 | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE FRONT DAMAGED PARTS AND COMPONENTS | \$ | 2,000.00 800 |
| 2 | TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND AFFECTED AREA. | \$ | 1,350.00 900 |
| 3 | TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS | \$ | 180.00 X |
| 4 | TO REMOVE AND REPLACE TAILGATE GLASS | \$ | 180.00 120 X |
| 5 | TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS | \$ | 120.00 60 |
| 6 | TO REMOVE AND REPLACE REVERSE SENSORS AND TEST FOR PROPER FUNCTION | \$ | 180.00 80 |

TOTAL :	\$	4,010.00
TOTAL PARTS :	\$	9,130.27
GRAND TOTAL :	\$	13,140.27

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repairer
Hy 900 10568
4 days
2/5
28/10/24
Res after repair

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	21/10/2024 10:01 (SGT)
Reported by	Actual Driver
Date of Accident	18/10/2024 08:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JURONG ISLAND
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ8750L
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	MOTORWAY CAR RENTALS PTE LTD
Company Reg No	1XXXXX927C
Email Address	ARC@MOTORWAY.COM.SG
Mobile Phone No	(Phone) +65-64662200
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Ssangyong
Model	Stavic
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	SD24V04867 /VPZ /R07

DRIVER

Name of Driver	MOHAMED FAZZIL BIN MOHD TAHIR
NRIC No	SXXXX319J
Date Of Birth	15/04/1967
Occupation	Outdoor
Driving Pass Date	02/10/1993
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	31 YEARS
Gender	Male
Mobile Number	(Phone) +65-96981543
Alt. Phone Number	-
Email Address	FAZZILTAHIR67@GMAIL.COM
Address	BLK 602 WOODLAND DRIVE 42 #07-61
Address complement	-
Postcode	730602
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE4155A
Vehicle Manufacturer	Scania

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Commercial vehicle
Work Permit No	LIU QIUTING
Contact Number	GXXXX807U
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



A -> SL2 8970L

B -> XE 4155A

Describe Circumstances of the Accident

Today Friday 18 October 2020. Time 0820 hrs.
I was driving vehicle no: SL28750 L. while
waiting for green light, traffic junction
in Jurong Island. Suddenly there is impact
into my rear-car. I go out to check, and
I found my car was hit from behind.
This vehicle number XE-4155 A is lorry
container. And was driven by foreigner
driver. (China man). Damage head to rear.
And no one injured.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





Ssangyong Stavic Diesel 2.0A

\$30,388 Instalment \$1,373/mth

PREMIUM AD

Apply for 2.48% loan Shortlist Loan Calculator



Overview Financial Photo Research

Depreciation	\$11,470 / year
Reg. Date	21-Apr-2016 (1yr 5mths 21days COE left)
Manufactured	2016
Mileage	133,000 km (15.6k / year)
Transmission	Auto
Engine Cap	1,998 cc
Road Tax	\$1,810 / year
Power	114.0 kW (152 bhp) View specs of the SsangYong Stavic Diesel (2013-2022)
Curb Weight	2,080 kg
Fuel Type	Diesel (Euro 5 Engine and Above)
COE	\$55,001
OMV	\$25,008
ARF	\$27,012
Dereg Value	\$22,949 as of today

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	927C
Vehicle Details	
Vehicle No.:	SLZ8750L
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2024
Vehicle Make:	SSANGYONG
Vehicle Model:	STAVIC 2.0D AUTO 2WD 9 SEATER
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	67196022688010
Chassis No.:	KPTV0B1TSHP122598
Maximum Power Output:	114.0 kW (152 bhp)
Open Market Value:	\$25,008.00
Original Registration Date:	16 Nov 2017
First Registration Date:	16 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$27,012.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2027
PARF Rebate Amount:	\$17,557.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,012.00
COE Rebate Amount:	\$14,920.00
Total Rebate Amount:	\$32,477.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 30 Oct 2024

OK