Surveyor:

REF: CS/LIP24100487/Knh3 (SNR 2582M)

Special Instruction:

L/SUM : $ 7,000 / REPAIR : 6 WORKING DAYS

ASSIGNMENT (Office)

From (Person): PATRICK YONG of LIP Date/Time: 28/10/2024

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: KTO AUTOMOBILE ASSESSORS

Workshop: WAH YU AUTOMOTIVE BODY WORK

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SNR 2582M Insured: PC 9957A

at Workshop m/s WAH YU AUTOMOTIVE BODY WORK Tel: 9736 0862

of 176 SIN MING DRIVE #05-90 SINGAPORE 575721

Policy No: Claim No: BVS24/0669

Sum Insured: Excess:

Make of Veh: D.O.A. 15/09/2024

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: **Confirmed with** **Final Fig** , days (Red $ / %; Original days)

Date/Time: 05/11/24 **Submit Final Fig** 3400 , 5 days (Red $ 3600 / 51 %; Original 6 days)

Date/Time	Action/Instruction
	mv $19k (est)
	lta $11140
	nv $7860

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to