

ASSIGNMENT

From: _____ Date: _____

Estn: _____

OD / TP RES / OD RES / EVA / INV / MV

To in _____ vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNC10549 Yr Regn: 2019 / August

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Swift C.D. 998

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 87740 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JSAAZC13S00300171

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: 185/55R16

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. 06/11/24

KT Motorwerk

Date / Time Action / Instruction

TP INC

COE Expiry: _____

Estimate given during: Yes (✓)
1st Survey: No ()

MV: _____

PV: _____

Nett: _____

0.15Z

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + R: \$ _____

Photos _____

Others _____

Report Format: _____

Report Form: _____