



ESTABLISHED 1984

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: AMANDA CHOOI

Ref: CS/INC24100501/Anh3e2(N)

Date: 25/02/2025

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SLJ 1935B	<b>Veh. Inspected</b>	SLZ 2653Z
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1301770-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZALYSA BINTE IBRAHIM	<b>Assign Date</b>	29/10/2024

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	OPEL CROSSLAND	<b>c.c</b>	1199
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	W0V7D9EDXJ4139216	<b>Colour</b>	BROWN
<b>Odometer</b>	149188 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60 R16	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	205/60 R16	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	BRIDGESTONE	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	27/10/2024	<b>Inspect Date / Time</b>	29/10/2024 ( 03:54 PM )
<b>Survey held at</b>	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**