



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI24060240/Uvh3
(BUDGET DIRECT INSURANCE) Date: 25/06/2024
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE SINGAPORE 239924 Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBK 7875P	Veh. Inspected	SGT 1298M
Policy No.	-	Coverage	0
Claim No.	C20030138/MC	Excess	\$0.00
Assign From	MICHAEL	Assign Date	25/06/2024

2. Vehicle Details

Make & Model	NISSAN QASHQAI 1.2 (A)	C.C	1197
Engine No.	HRA2307192A	Year of Reg.	23/12/2016
Chassis No.	SJNFEAJ11U1718637	Colour	BLUE
Odometer	94176 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60R17	DIAMONDBACK	7
L/H Front Tyre	215/60R17	DIAMONDBACK	7
R/H Rear Tyre	215/60R17	DIAMONDBACK	7
L/H Rear Tyre	215/60R17	DIAMONDBACK	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT MIRROR.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/06/2024	Inspection Date	27/06/2024
Survey held at	JOO HAK KEE AUTO PTE LTD 3007 UBI ROAD 1 #01-406 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408701		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days