

ASS. REC. BY:

REF:

SMO/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

50 Sarayan

Toyride
01-24

Insured:

2128

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

£ 7800h

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

/

PRS

EN repair cost £3-4k

V/Ly £1250h

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

F. Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Veh No:

PBN 2086A Yr Regn: 08, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB150R c.c. 149

Colour:

Green

A/C: Insured / Std / NI / NA

Sp. Reading

93635

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MCHKC 2885J. 5025984

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/70R17

R:

150/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

2

mm

Rear

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

22/10/24

D.O.I.

29/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.



JOYRIDE.CO PTE. LTD.
50 SERANGOON NORTH AVENUE 4 FIRST CENTRE #01-24
555856
Singapore

QUOTATION

QU-0002

Not Authorized
L1 Pay @ 125c/hr
Running After Paym

Date : 27-11-2024

Delivery Date : 27-12-2024

Ref# :

CB150R (FBN2066A)

#	Item	Qty	Rate	Amount	
1	Handle Bar	1.00 pcs	65.00	<i>DIY</i> 65.00	✓
2	Brake Lever	1.00 pcs	18.00	<i>DIY</i> 18.00	✓
3	Clutch Lever	1.00 pcs	22.00	<i>ln</i> 22.00	X
4	Mirror One Set	1.00 pcs	80.00	<i>Ad</i> 80.00	✓
5	OBV	1.00 pcs	250.00	<i>Ncl</i> 250.00	✓
6	Front Mudguard	1.00 pcs	65.00	<i>ln</i> 65.00	X
7	Front Fork Replacement	1.00 pcs	700.00	<i>ln</i> 700.00	✓
8	Front Rim Replacement	1.00 pcs	250.00	<i>ln</i> 250.00	X
9	Front Brake Disc	1.00 pcs	90.00	<i>ln</i> 90.00	X
10	Left Shroud Cover	1.00 pcs	60.00	<i>mycat</i> 60.00	✓
11	Radiator	1.00 pcs	180.00	<i>ln</i> 180.00	✓
12	Tank Cover	1.00 pcs	150.00	<i>ln</i> 150.00	X
13	Gear Pedal	1.00 pcs	25.00	<i>DIY</i> 25.00	✓
14	Foot Rest	1.00 pcs	28.00	<i>Ncl</i> 28.00	✓
15	Guard (Bracket)	1.00 pcs	45.00	<i>ln</i> 45.00	X
16	Left Pillion Foot Rest	1.00 pcs	20.00	<i>ln</i> 20.00	X
17	Front Number Plate	1.00 pcs	20.00	<i>ln</i> 20.00	✓
18	Front Signal Light Set	1.00 pcs	45.00	<i>Ncl</i> 45.00	✓
19	Handle Grip	1.00 pcs	25.00	<i>ln</i> 25.00	✓

#	Item	Qty	Rate	Amount
20	Left Switch	1.00 pcs	80.00	1m 80.00 X
21	Rear Top Box	1.00 pcs	120.00	nd 120.00 ✓
22	Headlight Stay	1.00 pcs	35.00	r 35.00 X
23	Labour	1.00 pcs	600.00	600.00 15d
Items in Total 23.00			Sub Total	2,973.00
			Total	SGD 2,973.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: