



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: EMILY TAN		Ref: CS/FCI24100516/Avp3q2(N) Date: 17/07/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4444K	Veh. Inspected	GBL 4550R
Policy No.		Coverage (\$)	0.00
Claim No.	D24009523MFCT	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	29/10/2024
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JN1YAAM20Z0001979	Colour	SILVER
Odometer	101079 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14C	TRIANGLE	6 mm
L/H Front Tyre	175/70 R14C	TRIANGLE	6 mm
R/H Rear Tyre	175/70 R14C	TRIANGLE	6 mm
L/H Rear Tyre	175/70 R14C	TRIANGLE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/10/2024	Inspection Date	29/10/2024
Survey held at	A-TEC AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #04-20 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	