



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MSIG INSURANCE (S) PTE LTD
4 SHENTON WAY #21-01
SGX CENTRE 2 SINGAPORE 068807

Ref: CS/MSG24100518/Enp3e2
Date: 21/11/2024
Code: MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SNM 1014U
Policy No.	-	Coverage	0
Claim No.	375757	Excess	\$0.00
Assign From	ASHLEY LOOI	Assign Date	29/10/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200	C.C	-
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	W1K2130802B096074	Colour	BLACK
Odometer	21367 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45 R18	GOODYEAR	6
L/H Front Tyre	245/45 R18	GOODYEAR	6
R/H Rear Tyre	245/45 R18	GOODYEAR	6
L/H Rear Tyre	245/45 R18	GOODYEAR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/09/2024	Inspection Date	05/11/2024
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days