

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC 24102519/UVH3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKF 9909H
 at Workshop m/s Hong Auto
 of _____
 Insured: SKL 32
 Policy No. _____
 Claims No. MT/1301606-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 72k
 IDAC Accident Rport: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKF 9909H Yr Regn: 12/06/12
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Mer Benz C180 c.c. 1597
 Colour: wh. fe A/C: Insured / Std / NI / NA
 Sp. Reading: 73271 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD 204045*2A724571
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 225/45-R17
 BS / DUN / EXNOVA / GY FS / LIZA / MIC / OHTSU / PIR / SUM /
 TOYO / YOKO or

Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 26/10/24 D.O.I. 29/10/24

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
8/11/24	002 10k. 60e until 31-05-2032 LTA @ 51289 2/5 @ 10,100 inland m2 lee (red 17,078.10, 62%)

Date/Time, File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1) Date/Time, File Return to?

2) _____

Add Fee: : Site Insp (\$ _____))
 : Interview (\$ _____))
 : Tech. Invs (\$ _____))
 : Weekend (\$ _____))

_____ S + RS, SI
 Photos
 Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	173C
Vehicle Details	
Vehicle No.:	SKF9909H
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 KOMPRESSOR
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	27191031355930
Chassis No.:	WDD2040452A724571
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$29,350.00
Original Registration Date:	12 Jun 2012
First Registration Date:	12 Jun 2012
Transfer Count:	0
Actual ARF Paid:	\$29,350.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2032
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$67,586.00
COE Rebate Amount:	\$51,289.00
Total Rebate Amount:	\$51,289.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 29 Oct 2024

OK

All Category
Filter 2

Save Search

Any status > 10 year(s) old
 Sort by Any Status, Date Posted (Newest)

33 Vehicles
Car Make
Car Model
Price Range
Depreciation
> 10 year(s) old...
Mileage

Mercedes-Benz C-Class C180K (COE till 01/2032)
\$75,800
\$10,440 /yr
19-Mar-2012 (7yrs 3mths COE left)
1,597 cc
4 Owners

Tip-top condition, service done regularly, well kept, full loan available with bank/in house loan, call now!
 Posted 29-Oct-2024

Compare

Mercedes-Benz C-Class C180K (COE till 03/2032)
\$78,800
\$10,610 /yr
25-May-2012 (7yrs 5mths COE left)
103,168 km
1,597 cc
3 Owners

Meticulous owner, religiously serviced every 10,000KM. Selling due to low usage. All wear and tear parts done up at in-house workshop! 100% loan of car price available, loan at 2.88% per annum! 1 to 1 exchange without cash top up! Hurry and call our sales advisers for more information! Best price guaranteed!
 Paragon Motor Pte Ltd|Posted 26-Oct-2024

Compare

PREMIUM AD

Mercedes-Benz C-Class C180 (COE till 02/2032)
\$86,888
\$11,840 /yr
02-Jan-2013 (7yrs 4mths COE left)
1,595 cc
3 Owners

Clean and neat interior. All wear and tear replaced. Well maintained.
 Posted 25-Oct-2024

Compare

DIRECT OWNER

Mercedes-Benz C-Class C180K (COE till 03/2032)
\$77,800
\$10,480 /yr
22-May-2012 (7yrs 5mths COE left)
190,000 km
1,597 cc
4 Owners

100% financing at an amazing rate from 3.18% per annum! Enjoy hassle free 1 to 1 exchange! Contact our friendly sales advisor for more details before it's off the market! We offer the best prices around!
 First Motoring|Posted 24-Oct-2024

Compare

Compare

HONG AUTO SERVICES

2 Kaki Bukit Ave 2, #01-28, Singapore 417921
 Tel: 6747 6436 / Fax: 6746 8868 / HP: 9853 5155
 Email: tchong4281@gmail.com

Not Authorized
 nu
 meras
 29/10/24
 2/5# 10,100
 take photo
 6 days.

Vehicle number: SKF9909H

Vehicle Made & Model: MERCEDES-BENZ C180

Qty	Part Items	Amount \$
1	Rear boot lid DD/BUK	2,236.77 ✓
1	Rear boot M/B star BMT	89.95 ✓
3	Rear boot M/B star clips @ 8.50 ALL	25.50 ✓
1	Rear boot emblem "C180" ALL	110.25 ✓
1	Rear boot emblem "KOMPRESSOR" ALL	110.25 ✓
1	Rear boot chrome moulding BMT/ALL	281.92 ✓
1	Rear boot outer handle TWI	126.20 ✓
1	Rear boot outer keyset 11	581.65 X
2	Rear boot licence lamps @ 86.55 11	173.10 X
1	Rear boot inner lock TWI	573.82 ✓
1	Rear boot inner lock cover 11	180.63 X
1	Rear boot inner trim 11	399.61 X
1	Rear boot w/strip TWI	281.81 ✓
2	Rear boot hinges - L/R @ 195.50 11	391.00 X
	Rear boot hinge covers - L/R @ 89.95 11	179.90 X
2	Rear boot stoppers @ 12.60 11	25.20 X
1	Rear boot lock striker 11	78.85 X
1	Rear bumper DIS 174.21	1,897.21 ✓
1	Rear bumper tow cover clw bumper	42.20 X
1	Rear bumper chrome moulding - CTR CR	281.60 ✓
2	Rear bumper chrome mouldings - L/R @ 252.06 ALL 180x2=360	504.12 ✓
1	Rear bumper top guide - CTR TWI	181.50 ✓
2	Rear bumper side guides - L/R @ 115 CR	230.00 ✓
2	Rear bumper side retainers - L/R @ 141.50 11	283.00 X
1	Rear bumper reinforcement BMT DIS 1,075.60	1,075.60 ✓
2	Rear bumper lower brackets @ 68.60 TWI	137.20 ✓
1	Rear end panel DD/BMT 1650.00	2,031.60 ✓
1	Rear end panel inner member R	811.55 X
1	Rear end panel garnish TWI	281.33 ✓
1	Rear exhaust silencer 11	1,655.50 X
1	Rear exhaust insulator 11	190.65 X
1	Rear fender - LH R	2,655.60 X
2	Rear fender tail panel garnishes @ 121.60 TWI/10,11	253.20 ✓
2	Rear fender inner trims - L/R @ 481.65 11	963.30 X

Vehicle number: SKF9909H

Vehicle Made & Model: MERCEDES-BENZ C180

1	Rear floor top board	11	580.60	X
1	Rear spare tyre well	11	481.66	X
1	Rear spare tyre retainer lock	11	211.43	X
2	Rear taillamps - L/R @ 810.53	CR	1,621.06	/
2	Rear taillamp panels - L/R @ 195.50	R	391.00	X
2	Front seat headrests - L/R @ 861.90	R	1,723.90	X
Sub-total			24,331.22	
Less 10%			2,433.12	
Total List			21,898.10	

Special Nett Items

1 set	Rear boot inner trim clip	11	50.00	X
1 set	Rear bumper clip	11	50.00	30 S/W
1 set	Rear no. plate	SVC	60.00	X
1 set	Rear reverse sensor - 4 pcs	Manufacturer	420.00	200 S/W
1	Rear reverse camera	11	480.00	X
1 set	Rear spare tyre well sealant	11	120.00	X
Total Special Nett			1,180.00	

Labour Charges

To check rear electrical wiring	80.00	20
To remove, refix rear interior trims to assist repair	120.00	60
To remove, refix rear reverse sensor / camera	80.00	30
To remove, refix rear exhaust systems	120.00	X
To respray undercoating	150.00	60
To remove, refix & reset headrest system	450.00	200
To respray painting & etc	1,500.00	1000
Panel beating, cut, weld, remove & replacing above parts	1,600.00	800
Total Labour	4,100.00	

ESTIMATE PARTS & LABOUR GRAND TOTAL \$

27,178.10

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rectified
- is subject to final approval from Insurance Company

Page 2 of 2

Acknowledged by Repairer
Signature: _____
Date: _____

7-11368.57
102
10231.72
230.
270
12631.72
202
10120.