

(08/11/13) WEL
ASS. REC. BY:

REF: CD/11124060242/Rma3

2004

ASSIGNMENT

WRE - 2026/007

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLH 8469A
at Workshop m/s BONNE MOTOR
of 2, Pandan Crescent
Insured: 111
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Est. or Market Value: 48K
IDAC Accident Report: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLH 8469A Yr Regn: 2016 1 OCT
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: TOYOTA PRIUS HB1-8 CVT c.c. 1798
Colour: GRGY AC: Insured / Std / NI / NA
Sp. Reading: 802564 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JTDKB3FU603535820
Gen. Cond: Good / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: NI / S/Rim / STD A/Rim or
Tyre Size: F: 125/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front		Rear	
R/Bal.	<u>6</u> mm	R/Bal.	<u>6</u> mm
L/Bal.	<u>6</u> mm	L/Bal.	<u>6</u> mm
D.O.A.	<u>25/06/24</u>	D.O.I.	<u>26/06/24</u>

Survey held at PANDAN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

REPAIR LIMIT - 31K

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS \$ _____

) Photos _____

) Others _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L	S1000006 / ICIII1	M/S Grab Rentals Pte. Ltd
64 Cecil Street	Document No.	3 Media Close
#06-02 IOB Building	0	#01-03/06
Singapore 049711	Document Date	Singapore 138498
Attn: Motor Claims Dept	25/06/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q1	17/10/2016	SLG8469A	0	31034	67/TP/SLG8469A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDKB3FU803535820	2ZRR954019	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-SMN8832K ACC DATE:25/06/2024 DRIVE IN:25/06/2024 DATE-IN:25/06/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				198.00
3	B	BP-MECH2 REPLACE SPORT RIM AND CONDUCT WHEEL BALANCING				198.00
4	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				198.00
5	B	BP-MECH2 REPLACE RH FRT SUSPENSION SYSTEM				792.00
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
7	B	BP-LAB2 REPLACE RH FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS				1480 3188.00
8	B	BP-RES2 RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS				2628 3936.00
9	1	U52119-47962 COVER, FR BUMPER	1.00	799.30		799.30
10	2	U53395-47040 SEAL, HOOD TO FR END	1.00	71.50		71.50
11	3	U52115-47050 SUPPORT, FR BUMPER	1.00	121.30		121.30
12	4	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	M/S Grab Rentals Pte. Ltd
	Document No. 0	3 Media Close #01-03/06 Singapore 138498
	Document Date 25/06/2024	Work: 65703925

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q1	17/10/2016	SLG8469A	0	31034	67/TP/SLG8469A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKKB3FU803535820	2ZRR954019	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	5	U52127-47907 COVER, FR BUMPER <i>Mis</i>	1.00	40.70		40.70
14	6	U53101-47081 GRILLE SUB-ASSY, <i>X</i>	1.00	484.10		484.10
15	7	U53301-47110 HOOD SUB-ASSY <i>repair</i>	1.00	1380.00		1380.00
16	8	U53801-47080 FENDER SUB-ASSY, FR <i>bu</i>	1.00	1488.90		1488.90
17	9	U53875-47070 LINER, FR FENDER, RH <i>su</i>	1.00	314.80		314.80
18	0	U47749-50090 CLIP, PIN HOLD <i>su</i>	2.00	2.50		5.00
19	1	U90467-07214 CLIP <i>su</i>	10.00	3.80		38.00
20	2	U53410-47130 HINGE ASSY, HOOD, RH <i>X</i>	1.00	81.80		81.80
21	3	U53213-47050 SUPPORT, RADIATOR, <i>cm</i>	1.00	109.40		109.40
22	4	U53835-47050 BRACKET, FR SIDE <i>cm</i>	1.00	81.10		81.10
23	5	U75374-47140 EMBLEM, SIDE PANEL <i>cm</i>	1.00	75.70		75.70
24	6	U81145-47691 UNIT, HEADLAMP <i>cm</i>	1.00	4063.00		4063.00
25	7	U81016-47690 COMPUTER SUB-ASSY, <i>?</i>	1.00	1334.80		1334.80
26	8	U81210-47020 LAMP ASSY, FOG, RH <i>cm</i>	1.00	1449.90		1449.90
27	9	U85315-47160 JAR, WASHER, A <i>dy</i>	1.00	303.30		303.30
28	0	U85319-47170 PIPE, WASHER, A <i>dy</i>	1.00	92.90		92.90
29	1	U67001-47153 PANEL SUB-ASSY, FR <i>repair</i>	1.00	1996.10		1996.10
30	2	U42611-47450 WHEEL, DISC <i>?</i>	1.00	2607.70		2607.70
31	3	U42602-47181 CAP SUB-ASSY, WHEEL <i>cm</i>	1.00	293.60		293.60
32	4	U48510-80815 ABSORBER SET, SHOCK, <i>cm</i>	1.00	616.00		616.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept				S1000006 / ICIII1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
				Document No. 0					
				Document Date 25/06/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2016	ZVW50R	AHXEBW Q1	17/10/2016	SLG8469A	0	31034	67/TP/SLG8469A		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU803535820		2ZRR954019	60	Sam San Joi	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
33	5	U48068-47060 ARM SUB-ASSY, ?			1.00	1166.90		1166.90	
34	6	U43330-19115 JOINT ASSY, LWR BALL ?			1.00	413.80		413.80	
35	7	U43550-47020 HUB & BEARING ASSY, ?			1.00	928.20		928.20	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Res</i> <i>4p 900/10068</i> <i>6 days</i> <i>26/06/24</i> <i>Res 24 paint</i>									
For & on behalf of Borneo Motors (Singapore) Pte Ltd				Customer's Signature		Charge Summary		Total	
Please acknowledge receipt of vehicle						Parts		29,203.80	
						Labour		2,628.34	
						Sublet			
						Lubrication/Fluid			
						Others			
						GST 9.00%		Less	
						Amount Due		31,832.14	

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	200G

Vehicle Details

Vehicle No.:	SLG8469A
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ZRR954019
Chassis No.:	JTDKB3FU803535820
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	17 Oct 2016
First Registration Date:	17 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$5,412.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Oct 2026
PARF Rebate Amount:	\$3,247.00

Intended COE Rebate Details

COE Expiry Date:	16 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,501.00
COE Rebate Amount:	\$12,772.00
Total Rebate Amount:	\$16,019.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 27 Jun 2024

OK