

JC Motor Consultancy

UEN No: 53383584D // Email: jcmotorconsultancy@gmail.com

Vehicle number: SJV2177B

Vehicle Made & Model: HYUNDAI AVANTE

Qty	List Items		Amount \$
1	Rear bumper	494.20 De/torn	651.50 ✓
1	Rear bumper sponge	torn	180.60 ✓
1	Rear bumper reinforcement	one	410.50 ✓
2	Rear bumper reinforcement stays - L/R @ 115	3mf	230.00 ✓
6	Rear bumper brackets @ 65.50	1m	393.00 2pcs
1	Rear boot lid	2	1,528.10 X
1	Rear boot logo	1m	48.60 ✓
1	Rear boot emblem "AVANTE"	2m	62.20 ✓
1	Rear boot emblem "S"	1m	48.60 ✓
2	Rear boot lamps - L/R @ 210.50	11	421.00 X
1	Rear boot outer garnish	one	181.90 ✓
1	Rear boot inner lock	SVC	190.60 X
1	Rear boot w/strip	11	161.90 X
1	Rear end panel	DD/1m	527.60 ✓
1	Rear end panel garnish	11	161.20 X
1	Rear floor board	11	460.20 X
2	Rear fender inner trims - L/R @ 411.50	11	823.00 X
2	Rear taillamps @ 311.60	one	623.20 ✓
Sub-total			7,103.70
Less 20%			1,420.74
Total List			5,682.96

Not Authorized
due
mercant
30/10/24
2/5 3300/
wh phs. Atk exp
H days

T- 2938.4
202
7,235.72
S.N-230
L- 1560
4140.72
22
3312

Vehicle number: SJV2177B

Vehicle Make & Model: HYUNDAI AVANTE

Special Nett Items

1 set Rear bumper clip	RM	50.00	30
1 set Rear boot inner trim clip	SU	50.00	X
1 set Rear reverse sensor	Molfluctum	280.00	200
Total Special Nett		380.00	

Labour charges

To remove, refix rear electrical wiring	50.00	20
To remove, refix rear interior trims to assist repair	120.00	80
To remove, refix rear reverse sensor / camera	80.00	30
To respray undercoating	80.00	30
To respray painting and etc.	1,200.00	800
Panel beating, cut, weld, remove & replacing above parts	1,200.00	600
Total Labour	2,730.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 8,792.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 2 of 2
Acknowledged by Repairer

Signature:

Date: