



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: FIONA SHEN

Ref: CS/INC24100529/Aqh3m4(N)

Date: 19/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 3094C	Veh. Inspected	SMY 7306L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1301804-001	Excess (\$)	0.00
Assign From	JULIET KOH	Assign Date	30/10/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDGG20W40J004847	Colour	WHITE
Odometer	172045 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/10/2024	Inspect Date / Time	30/10/2024 (01:26 PM)
Survey held at	AUTO UNITED SG PTE LTD 1 KAKI BUKIT AVENUE 6, #01-92, AUTOBAY@KAKI BUKIT, SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------