

ASS. REC. BY:

REF: 1702/

CS/FCI24100532/Knp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s Lim Yew Boo

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$25K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

09/27

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGY 4673J Yr Regn: 091 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis (A) c.c. 1598

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 164525 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0538EC107154129

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / R/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Ntexen

Front

Rear

R/Bal. 0 mm

R/Bal. 9 mm

L/Bal. 0 mm

L/Bal. 9 mm

D.O.A. 26/10/24

D.O.I. 18/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/11/21 Amp @ 2200h Cash (Red, \$3562.14, 61%)

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ - RS. \$

Fuel

Others

TOTAL

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 442I

Vehicle Details

Vehicle No.: SGY4673S
Vehicle to be Exported: Yes
Intended Deregistration Date: 16 Nov 2024
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Silver
Manufacturing Year: 2007
Engine No.: 3ZZ4691850
Chassis No.: MR053ZEC107154129
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$14,757.00
Original Registration Date: 27 Sep 2007
First Registration Date: 27 Sep 2007
Transfer Count: 3
Actual ARF Paid: \$16,233.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Sep 2027
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$44,081.00
COE Rebate Amount: \$12,612.00
Total Rebate Amount: \$12,612.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 16 Nov 2024

OK

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

*Not Authorized
 11/11/24 @ 2200hrs
 spraying Area Paint
 4 days*

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Estimate : TP24/034

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Date : 16/11/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 16/11/2024
 Claim No. : D24008620MFCT/CTPL/TPD-2
 Reference : LYB/SGY4674S/MSFirst/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	REAR BUMPER		
2.	2	REAR BUMPER BRACKETS		
3.	2	REAR BUMPER RETAINER		
4.	1	REAR LID		
5.	1	REAR LID RUBBER		
6.	1	REAR LID LOCK (UPPER)		
7.	1	REAR LID LOCK (LOWER)		
8.	1	REAR TAILEND PANEL		
9.	1	REAR TAILEND INNER GARNISH		
10.	2	REAR TAILLAMP LOWER PANEL		
11.	1	REAR BUMPER LIP SPOILER		

<i>also</i>	70.20	<i>Be/mbim</i>	501.70	<input checked="" type="checkbox"/>
<i>also</i>	30.20	<i>n</i>	140.40	<input checked="" type="checkbox"/>
		<i>n</i>	60.40	<input checked="" type="checkbox"/>
		<i>n</i>	641.60	<input checked="" type="checkbox"/>
		<i>n</i>	161.80	<input checked="" type="checkbox"/>
		<i>n</i>	90.70	<input checked="" type="checkbox"/>
		<i>n</i>	42.10	<input checked="" type="checkbox"/>
		<i>n</i>	666.10	<input checked="" type="checkbox"/>
		<i>n</i>	45.15	<input checked="" type="checkbox"/>
	121.60	<i>n</i>	243.20	<input checked="" type="checkbox"/>
		<i>n</i>	551.30	<input checked="" type="checkbox"/>
			3,144.45	
			786.11	
			2,358.34	

List Total S\$:
 25.00% Discount S\$:

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	REAR EMBLEM '1.6E'		
2.	1	REAR EMBLEM 'VVTI'		
3.	1	REAR EMBLEM 'COROLLA'		
4.	1	REAR EMBLEM 'ALTIS'		
5.	2	REAR EMBLEM LOGO 'TOYOTA'		

<i>na</i>	40.20	<i>na</i>	40.20	<input checked="" type="checkbox"/>
<i>na</i>	39.70	<i>na</i>	51.30	<input checked="" type="checkbox"/>
<i>na</i>	40.20	<i>na</i>	40.20	<input checked="" type="checkbox"/>
<i>na</i>	57.90	<i>na</i>	115.80	<input checked="" type="checkbox"/>
			287.20	

Nett Total S\$:

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP24/034

Date : 16/11/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 16/11/2024
 Claim No. : D24008620MFCT/CTPL/TPD-2
 Reference : LYB/SGY4674S/MSFirst/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		SPECIAL NETT ITEMS :		
1.	4	REAR TAILEND PANEL TEROSTAT SEALANT	54.20	na 216.80 X
2.	1 SET	REAR TAILEND INNER GARNISH CLIPS		na 12.00
3.	12	REAR RIVET	2.80	na 33.60 X
4.	1 SET	REAR REVERSE SENSOR		na 220.00 X
5.	1	REAR BUMPER LIP SPOILER SEALANT		na 54.20
6.	1	REAR BUMPER LIP SEALANT STRIP		na 120.00
7.	5	REAR BUMPER FASTENER	10.00	na 50.00
8.	5	REAR BUMPER EXTENSION FASTENER	10.00	na 50.00 X
9.	5	REAR BUMPER EXTENSION GROMMET SCREW	10.00	na 50.00 X
		Special Nett Total S\$:		806.60
		LABOUR :		
		TO CHECK ALIGNMENT ON AFFECTED EXHAUST		na 80.00 X
		LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS		120.00 50/
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS		150.00 30/
		TO TRANSFER BOOT LID PARTS & FITTING TO NEW BOOT LID		na 80.00 X
		TO CHECK WATER SEEPAGE		80.00 20/
		TO REPAIR, PANEL BEAT, CUT & WELD ON AFFECTED PANEL,		

CONTINUE / ...

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 20051400L

MS FIRST CAPITAL INSURANCE LIMITED
 16 RAFFLES QUAY #42-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP24/034

Date : 16/11/2024
 Vehicle Num. : SGY 4673S
 Make/Model : TOYOTA ALTIS-2007
 Chassis/Eng# : MR053ZEC107154129/3ZZ4691850
 Accident Date : 16/11/2024
 Claim No. : D24008620MFCT/CTPL/TPD-2
 Reference : LYB/SGY4674S/MSFirst/TP/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR TO REPLACE THE ABOVE PARTS		800.00 <i>600</i>
		TO PUTTY, PRIMER & SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, SPOILER, TAILLAMP LOWER PANEL & SENSOR.		1,000.00 <i>800</i>
		Labour Total S\$:		2,310.00

E. & O.E.

Total S\$:

5,762.14
=====


 for LIM YEW BOO SPRAY PAINT CO.