ASS. REC. BY: Tayph - KEF: US (T124	1100542/1043
•,,	GNMENT
From: Date:	Veh No: SLP 868L Yr Regn: 2019, 02
Eslimated Cost:	Type: (A.Ca) / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD (TP) WS   TP RES   OD RES   EVA   INV   MV	Truck / Traller or
To Inspect Vehicle No:	Make: Andi Ce 8 c.c 2995
at Workshop m/s	Colour Back A/G: Insured / Std / NI / NA
of .	Sp.Reading \$1997 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/NO: WAY222 F19 K-P011590
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Sleering: Inorde / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh;	Modl: NII / SRim / STD A/Rim or
- ALAAn	Tyre Size: F: 295 35 823
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIP) SUMI /
Bal. or Market Value;	Front Rear
IDAC Accident Rport:Consistent? : Yes or No	R/Bal, R/Bal, Mm - R/Bal, Mm -
GIA / PR Seem Consistent? : Yes or No	L/Bal. C mm L/Bal. 6 mm
Est Repairs: days Res.: Yes or No	D.O.A. D.O.I. 3-1024
Lum Sum: % 3 Val.: Yes or No	Survey held at Purnim Benoi
CA / REV / REP. / 24 HRS  Vehicle: IN / OUT	Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop-or
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
Data/Time, File Pass to? : Prell. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Add Fee	1 2440 21
Mary 1 Mary 1	: Interview (\$ ) Photos

: Tech. Invs (\$

: Meel:end (#

Citiens

Pop Formal:

Lump Sum / LBJ: 75

# **♦ PREMIUM** AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

: ACCIDENT REPAIRS

WORKSHOP

: UBI ROAD 1

CONTACT NO

: 6366 2323

FAX NO

: 6841 1183

REFERENCE

: PA/TP/0827/2024/KS

DATE

: 30-Oct-24

WIP

: 36298

VEHICLE NOT IN WORKSHOP, KINDLY ARRANGE FOR SURVEY ON 30/10/2024

YOUR INSURED VEH NO : SLM 5444 J

China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

OWNER'S NAME

MR CHONG GUANG WEI WESLEY

**ADDRESS** 

: 81 LONG N TELOK KURAU

#05-01

SINGAPORE 425231

TELEPHONE

: HP +65 98260278

TYPE OF CLAIM

THIRD PARTY CLAIM : DMPPHQ24-007300

POLICY NO

: SLP 868 L

VEHICLE NO MODEL CODE

: AUDI Q3 3.0 TFSI QU

MODEL YEAR

: 27/2/2019

ENGINE NO

: DCB 060352

CHASSIS NO

: WAUZZZF19KD011590

MILEAGE

KM

DATE IN


ESTIMATED BY

: JOHNNY BOO / ALLAN WU

ACCIDENT DATE

: 30-Oct-24

PLACE OF ACCIDENT : 91 MARINE PARADE RD, SINGAPORE 449314





55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 868 L.

				MATED ARGES	SURVEYOR'S RECOMMENDATIONS
S/N	NATURE OF JOBS			IKUES	
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N	\$	280.00 "	
2	TO REMOVE AND REINSTALL RHS WING MIRROR TO FACILITATE DOOR PAINTING	S/N	\$	600.00	plut.
3	TO REMOVE AND RENEW AIRCOND CONDENSOR, CHARGE AIR COOLER AND RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N	\$	1,800.00	?
4	TO REMOVE AND RENEW RHS CHARGE AIR COOLER.	S/N	\$	880.00	
5	TO CARRY OUT VACUUM AND REGAS R1234.	S/N	.\$	1,200.00	7
6	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		1200	3.00 10,200.00	0
7	TO RESPRAY FRONT AND REAR BUMPER, FRONT AND REAR BUMPER SPOILER, RADIATOR GRILLE TRIM, RHS FRONT FENDER, BONNET, RHS FRONT DOOR, RHS A-PILLAR, BOTH FRONT AND REAR WHEEL ARCH TRIMS AND RHS FRONT DOOR LOWER COVER.		12 <i>0</i> 0 \$	6 & 0 12,000.00	20
8	TO RENEW RHS FRONT RIM AND CARRY OUT/POST COMPUTERISED WHEEL ALIGNMENT.	S/N	\$	620.00	/
9	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N	\$	3,200.00	7.
10	TO CARRY OUT CALIBRATION FOR 360 CAMERA SYSTEM WITH VAS TOOLS.	S/N	\$	800.00	7
11	TO CARRY OUT DIAGNOSTIC CHECK,	S/N	\$	480.00	
	TOTAL LABOUR CHARGES	:	\$	32,060.00	_





55 UBI ROAD 1, SINGAPORE 408699 TEL : 6366 2323 FAX : 6841 1183 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 868 L.

## DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				1. /
1	FRONT BUMPER	1	\$ 4,553.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 422.00	
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 150.00	
4	FRONT BUMPER FRAME - RH (BRILLIANT BLACK)	1	\$	miy/
5	FRONT BUMPER COVER - RH (BRILLIANT BLACK)	1	\$ 103.00	misu
6	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 348.00	cun /
7	FRONT BUMPER TRIM - CENTER (DARK CHROME MATT)	1	\$ 506.00	dis
8	FRONT BUMPER GRILLE	1	\$ 316.00	dis-
9	FRONT BUMPER CLOSING ELEMENT	1	\$ 367.00	cira
10	FRONT UNDERRUN BAR	1	\$ 1,011.00	cua -
11	FRONT BUMPER TRIM - PLATINUM GREY	1	\$ 675.00	ong -
12	FRONT BUMPER TRIM	. 1	\$ 620.00	9
13	FRONT TOWING EYE COVER	1	\$	Mis-
14	FRONT DECORATIVE FRAME - RH	1	\$ 4,154.00	cua/
15	FRONT AIR GUIDE GRILLE - RH	1	\$ 549.00	mis
16	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 36.00	nais
17	RADIATOR GRILLE	1	\$ 3,188.00	en/
18	AUDI EMBLEM	1	\$ 210.00	mais mis
19	"RSQ8" EMBLEM	1	\$ 202,00	.0.
20	RADIATOR GRILLE COVER - RH - GLOSSY BLACK	1	\$ 152.00	7
	SUB TOTAL SPARE PARTS	1	\$ 17,749.00	_

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183 EMAIL: NORA,KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 868 L.

### **DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
	44.44.504		94.00	9
21	RADIATOR GRILLE - REAR END COVER	1	\$	6
22	"360" DEGREE CAMERA	1	\$ 1,253.00	*
23	"360" DEGREE CAMERA COVER CAP	1	\$ 234.00	*
24	"360" DEGREE CAMERA BRACKET	1	\$ 116.00	
25	"360" DEGREE CAMERA SECURING PLATE	1	\$ 18.00	
26	FRONT PARKING AID SENSOR	1	\$	dis
27	FRONT PARKING AID SENSOR - OUTER	1	\$ 315.00	mis
28	FRONT PARKING AID SENSOR SEAL RING	6	\$ 17.00	Nel /
29	FRONT BUMPER WIRING SET	1	\$ 751.00	?
30	FRONT BUMPER GUIDE SECTION - RH	1	\$ 56.00	219
31	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 46.00	dis-
32	FRONT BUMPER BRACKET - RH	1	\$ 43.00	7
33	FRONT BUMPER TOP COVER	1	\$ 164.00	7
34	FRONT FOAM FILLER PIECE	1	\$ 215.00	フ
35	FRONT REINFORCEMENT BEAM	1	\$ 1,176.00	61-
36	"CAUTION" STICKER	1	\$ 25.00	X
37	"WARNING" STICKER	Î	\$ 38.00	×
38	"OIL CAUTION" STICKER	1	\$ 25.00	×
39	LED HEADLIGHT WITH MATRIX BEAM - RH	î	\$	cu/
40	LED HEADLIGHT P. C BOARD - RH	1	\$ 1,182.00	?
	SUB TOTAL SPARE PARTS	:	\$ 21,372,00	-
		,	 <del></del>	€

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 868 L.

#### **DAMAGED PARTS & PRICES**

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
					0
41	LED HEADLIGHT FAN - RH	1	\$	481.00	i
42	LED HEADLIGHT POWER MODULE	1	\$	904.00	
43	LIFT CYLINDER BRACKET - RH	1	\$	30.00	n1)-
44	LIFT CYLINDER BRACKET REPAIR SET - RH	. 1	\$	28.00	an's
45	LIFT CYLINDER - RH	1	\$	238.00	nis
46	LIFT CYLINDER HOSE	. 1	\$	46.00	mis my
47	LIFT CYLINDER HOSE	1	\$		mis-
48	LED HEADLIGHT MOUNTING - RH	1	\$	147.00	ens/
49	FRONT FENDER - RH	1	\$	2,912.00	bul-
50	FRONT FENDER ATTACHMENT PARTS - RH	1	\$.		bt-
51	FRONT FENDER BRACKET - RH	1	\$		
52	FRONT FENDER BRACKET - RH	. 1	\$	80.00	4-
53	FRONT FENDER BRACE - RH	1	\$	265.00	51
54	FRONT FENDER CLOSING ELEMENT - RH	1	\$	67.00	2
55	FRONT WHEEL HOUSING LINER - RH	1	\$	301.00	
56	FRONT WHEEL HOUSING LINER - RH	1	\$	301.00 0	
57	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$		ne (_
58	HEADLIGHT COVER - RH	1	\$		_
59	BONNET	1		127.00	
60	BONNET ATTACHMNET PARTS		\$	5,615.00	7
	CUR TOTAL ORANG DATE	1	\$	141.00 🗴	
	SUB TOTAL SPARE PARTS		\$	11,959.00	
	ALL CUADOES ADE NOT BLOWN	=		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT,





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 868 L.

#### DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
					×
61	BONNET HINGE - LH / RH	2	\$	420.00	
62	BONNET GAS FILLED STRUT	1	\$	53.00	Υ΄
63	BONNET IMPACT PROTECTION - LH / RH	1	\$	114.00	X
64	BONNET IMPACT PROTECTION - CENTER	1	\$	38.00	×.
65	BONNET STRIKER - LH / RH	2	\$	298.00	×
66	BONNET BOWDEN CABLE	1	\$	71.00	? (
67	BONNET LOCK WITH MICRO SWITCH	2	\$	491.00	×
68	BONNET LOCK CABLE	1	\$	92.00	1
69	BONNET LOCK CABLE	1	\$	12.00	?
70	FRONT WHEEL ARCH COVER - LH / RH	2	\$	1,372.00	mis-24, Ly new
71	LOCK CARRIER	1	\$	1,503.00	mis 24, ly new
72	LOCK CARRIER SIDE MEMBER	1	\$	539.00	?'
73	LOCK CARRIER BRACKET - RH	1	\$	80.00	?
74	LOCK CARRIER BRACKET - RH	1	\$	46.00	7
75	RADIATOR AIR GUIDE - RH	1	\$	71.00	<u> </u>
76	RADIATOR AIR GUIDE - UPPER	1	\$	97.00	ר
77	RADIATOR AIR GUIDE - LOWER	1	\$	54.00	?
78	RADIATOR COOLANT	6	\$	332.00	· 7
79	CHARGE AIR COOLAR	1	\$		1. 1
80	CHARGE AIR COOLAR HOSE CLAMP	1	\$	1,386.00 <i>)</i> 24.00	74/
	SUB TOTAL SPARE PARTS	*	Ψ	24.00	this
	OSS TOTAL OF ARE PARTS	:	\$	7,093.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 868 L.

#### DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
			 7	
81	CHARGE AIR COOLER PRESSURE HOSE	1	\$ 273.00 {	
82	CHARGE AIR COOLER PRESSURE HOSE	1	\$ 229.00	
83	CHARGE AIR COOLER PRESSURE PIPE	1	\$ 117.00	
84	CHARGE AIR COOLER PRESSURE HOSE	1	\$ 130.00 (	
85	CHARGE AIR COOLER AIR GUIDE	1	\$ 109.00	4
86	CHARGE AIR TUBE	1	\$ 336.00	
87	COVER FOR CHARGE AIR COOLER	1	\$ 27.00 ?	
88	HORN	1	\$ 251.00 A	13-
89	HORN BRACKET - RH	1	\$ 35.00	(
90	"S-LINE" EMBLEM	. 1	\$ 149.00 h	u-
91	ROOF MOLDING - RH	1	\$ 675.00	
92	ROOF FRAME SEAL	1	\$ 193.00 7	
93	FRONT DOOR WINDOW SLOT SEAL - RH OUTER	1	\$ 260.00 is	W/
. 94	FRONT DOOR LOWER COVER - RH	1	\$ 603.00 X	
95	FRONT ALUMNIUM RIM - RH	1		11
96	FRONT ALUMNIUM RIM RUBER VALVE - RH	1	\$	ei/
97	FRONT WISHBONE LINK	1	\$ 1,052.00 7	
98	FRONT SUSPENSION GUIDE	1	\$ 769.00	
99	FRONT UPPER ARM GUIDE - RH FRONT	1	\$ 465.00 7	
100	FRONT UPPER ARM GUIDE - RH REAR	1	\$ ,	
	SUB TOTAL SPARE PARTS	,	 465.00	
	STATE I ANIG	1	\$ 6,143.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.



## ♦ PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 868 L.

## DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
3/14	1,11,10,220,1111,1111,111				7
101	FRONT WHEEL BEARING HOUSING - RH	1	\$	990.00	à
102	FRONT SWIVEL JOINT - RH	1	\$	198.00	
103	FRONT WHEEL HUB - RH	1	\$	533.00	'/ 'a
104	FRONT WHEEL BEARING - RH	1	\$	305.00	7
105	FRONT SUSPENSION FORK - RH	, 1	\$	450.00	•
106	FRONT ANTI-ROLL BAR - RH	1	\$	650.00	4
107	FRONT ANTI-ROLL BAR CLAMP	2	\$	116.00	<i>(</i>
108	FRONT SHOCK ABSORBER - RH	1.	\$	3,829.00	*
109	FRONT DRIVE SHAFT - RH	1	\$	3,121.00	<b>X</b>
110	FRONT LEVEL SENSOR - RH	1	\$	419.00	X
111	FRONT SUPPORT FRAME	1	\$	4,733.00	?
112	STEERING GEAR	1	\$	7,735.00	1
113	STEERING GEAR TIE ROD - RH	1	\$	188.00	1
114	STEERING GEAR TIE ROD END - RH	1	\$	249.00	`
115	FRONT WHEEL ARCH COVER - LH / RH	2	\$	892.00	10
116	FRONT WHEEL COVER - RH	1	\$	139.00	97
117	FRONT SUSPENSION SCREWS, BOLTS & NUTS		\$	400.00	· '
118	FRONT BUMPER DIFFUSE	1	*		1
119	FRONT NO PLATE	S/N	\$		41-
120	SUNDRIES	G/IV		60.00	2
	TOTAL SPARE DARTS		\$	1,000.00	•
	TOTAL LABOUR CHARGE	:	\$	90,323.00	
	TOTAL LABOUR CHARGES	:	\$	32,060.00	
	GRAND TOTAL	:	\$	122,383.00	-
	ALL CHARGES ARE NOT INCLUSIVE OF COT			,000.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.



# **♦ PREMIUM** AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE **AUTHORISED DATE** 

**EXCESS COST** LIABILITY

REMARKS

PLEASE NOTE

Taylor 9749579 (6756)561
Solays

Who 36/10/24 & 3pm

In horas before paint.

Tenflu (1/hourb.com.

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE

PROGRESS OF REPAIR, WE SHALL INFORM YOU

ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR

APPOINTMENT.

YOURS FAITHFULLY. PREMIUM AUTOMOBILES PTE LTD

#### LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged panis: during resurvey
- · Parts prices are subject to nonfirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is all: ren
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Pepairer

Signature:

Date:

JOHNNY BOO BODY REPAIR MANAGER ALLAN WU **CLAIMS CONSULTANT** 



## **SINGAPORE ACCIDENT STATEMENT**

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# CALL STATEMENT AND AND AND AND ACCIDENT STATEMENT A

28/10/2024 18:49 (SGT) Date of First Submission Both Policyholder and Actual Driver Reported by 27/10/2024 20:07 (SGT) Date of Accident THE STREET AND THE PROOF PROFESSION AND COMMENT OF THE PROPERTY OF THE APPEARANCE OF THE PROPERTY OF THE PROPE 91 Marine Parade Rd, Singapore 449314 Exact Location of Accident MARINE BLUE CONDOMINIUM CARPARK ENTRANCE Additional Location Information Country/State of Loss Singapore

#### 

DETAILOR	THE WIND ME
Vehicle Registration Number	SLP868L
INSURED/POLICYHOLDER	
the second second	
Is company?	
Is company?	No
Name Of Registered Owner NRIC No	CHONG GUANG WEI WESLEY
Email Address	SXXXX958D
Mobile Phone No	WESCGW@GMAILL.COM
Alternative Phone No	(Phone) +65-98260278
Alternative Filone NO	+65-88140388
T1 12	
VEHICLE PARTICULARS	
Manufacturer	Accel
Model	Audi
Variant	Q8
=xact purpose for which vehicle was being used at time of	3.0 TFSI QU
accident	Private use
We you claiming under your own insurance policy for repair to	Finale use
our vehicle?	No - Claiming this
/ehicle Category	No - Claiming third party Private car
ransmission	Auto
C to transfer on more faller and faller and faller	2995
ehicle Fuel	2990
irst Regisration Date	
nassis no	-
ffective Date/Time of Ownership	•
XX   V	<b>□</b>
NSURANCE COMPANY	
ame of Insurance Company	
A CONTRACTOR OF THE PROPERTY O	Fa.

Policy Number / Cover Note Number

EQ Insurance Company Ltd DMPPHQ24-007300

DRIVER



	CHONG GUANG WEI WESLEY
Name of Driver	CHONG GUANG WEI WES
Name of Driver	SXXXX958D
Name of Diver	12/11/1984
Date Of Birth	Indoor
Occupation	16/02/2004
Driving Pass Date	3
Driving License Pass Class	Valid
Driving License Validity	20 YEARS AND 8 MONTHS
Driving experience	
Gender at a control on the control of the co	Male
Mobile Number	(Phone) +65-98260278
Alt. Phone Number	+65-88140388
Fmail Address	WESCGW@GMAILL.COM
Address	91 MARINE PARADE ROAD
Address complement	#05-05, MARINE BLUE
Postcode	449314
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Principle in the state of the s	·
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry
To Article and Table 2	
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	-
Number of Passengers (Including Driver)	Yes
	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	No
Translator's ID	
Translator's phone number	-
Translator's email	-
Original language used in the statement	-
Original language used in the statement	-
PASSENGER 1	
Name	Motor
Gender	NGUYEN THI THU HANG
CONTROL OF THE STATE STATES CONTROL STATE SECTION OF THE STATES OF THE S	Female
1	
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	INU
	•
OLD CHARTANICES OF ACCIDENT	

CIRCUMSTANCES OF ACCIDENT

I WAS ENTERING MY CONDOMINIUM CARPARK. AFTER TURNING AROUND THE BEND, A BLUE CAR WHICH WAS DRIVING IN THE OPPOSITE DIRECTION ON THE CENTER LINE COLLIDED INTO MY CAR. MY CAR WAS WITHIN MY LANE AT ALL TIMES.

ATTACHMENT(S)

Are accident photos available for attachment?

# DETAILS OF OTHER VEHICLE PROPERTY II

Vehicle Registration Number Vehicle Manufacturer	SLM5444J Audi A1
Vehicle Model	Ai
Vehicle Model	•
Vehicle Variant	Blue
Vehicle Colour	Private car
Name of Driver	\ <b>-</b> X
Contact Number	-
	-
Address complement	-
	_
Incurance Company Name	
Of Damago	-
a standard damaged in accident	-
No. Of Passenger (Including Driver)	-

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Pease report correctly the details of the accident to speed up the clams process.
- 2 This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful insrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the clams:
- (ii) investigating the accident and/or my claims;
- (a) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) admnistering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time 28/10/24

Sketch Plan

Oriver's Signature (If driver is not the policyholder) / Date & Times

footage

Witnessed by Reporting Centre Personnel

the video -

& accident scong pholy

Describe Circumstances of the Accident

he opposite direction on	inium Carpark. After turning around the bend, the center line collided into my car. My car wa	as within my lane at all time.
ere were no reported inju	rion	
ere were no reported my	ines.	
	· ·	
		water with the state of the sta
	and the second s	
	· · · · · · · · · · · · · · · · · · ·	
<del>~</del>		
		THE WATER COMMITTEE TO THE PARTY OF THE PART
	The second secon	
		· · · · · · · · · · · · · · · · · · ·
		<del>490 - 19 - Arristo Harasia, de la companya de la comp</del>
1 <del>-1</del>		A CONTRACTOR OF THE CONTRACTOR
		William Lill Std. St. St. St.
The state of the s		A
eclaration		
cciataboli		
le declare the foregoing particula	s are true in every respect.	
	* 46.00	
1 ^ /		(40 ° 0)
		(1) D'(2)
		13
olicyholder's Signature / Date &	Driver's Signature (# driver is not the policyholder) / Date & Time	N. A. 1.1
me 25/10/24	Policy (tolder) / Date	Witnessed by Reporting Centre Personnel Ton Foory
		Lisurine Inal h