

## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

*Jumani*

TP INSURER:  
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

### PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/10/2024
Vehicle Reg. No.:	SH6503J	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV, 1.6 (A)	Vehicle Reg. Date:	02/04/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU192044	Chassis No:	KMHC851CVKU141542
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

### COST OF CLAIMS

	Amount
Parts	6,054.36
Miscellaneous Items	12.00
Labour	3,775.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>9,841.36</b>
<b>+ GST 9.00% (S\$)</b>	<b>885.72</b>
<b>Nett Amount (S\$)</b>	<b>10,727.08</b>

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

A. 200  
 Estimate  
 to Qty Part  
 Misc

**REPAIR DETAILS**

**Reference**

**Part Source:** (Last Synchronised: 30 Oct 2024)  
**Parts:** N/A HYUNDAI AE IONIQ HEV 1.6 (A) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** ComfortDelGro Engineering Pte Ltd/SH6503J/30/10/2024 14:00  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER ASSY <i>x R</i>	20.00	0.00	*481.10 FL
2	10		*FRT BUMPER CLIPS <i>x nn</i>	20.00	0.00	*22.00 FL
3	1		*FRT BUMPER SIDE BRACKET LH <i>x nn</i>	20.00	0.00	*35.00 FL
4	1		*FRT FENDER LH <i>nn</i>	20.00	0.00	*588.80 FL /
5	1		*FRT FENDER EMBLEM LH <i>nn</i>	20.00	0.00	*26.60 FL /
6	1		*FRT DOOR ASSY LH <i>nn</i>	20.00	0.00	*1,797.20 FL /
7	1		*REAR DOOR ASSY LH <i>x R</i>	20.00	0.00	*1,789.90 FL
8	1		*REAR FENDER LH <i>x R</i>	20.00	0.00	*1,768.30 FL
9	1		*REAR REAR BUMPER ASSY <i>x R</i>	20.00	0.00	*459.40 FL
10	10		*REAR REAR BUMPER CLIPS <i>x nn</i>	20.00	0.00	*22.00 FL
11	1		*FRT DOOR COMFORT LOGO <i>nn</i>	0.00	0.00	*75.00 F / nett
12	1		*REAR DOOR APPS LOGO <i>nn</i>	0.00	0.00	*80.00 F / nett
13	1		*PATROL STICKER <i>x nn</i>	0.00	0.00	*30.00 F
14	1		*WHEEL RIM CAP FRT <i>FL</i>	20.00	0.00	*346.40 FL /

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)** 7,521.70  
 - List Item Discount on L Items (\$\$) 1,467.34  


---

**Total Parts (\$\$)** 6,054.36

ComfortDelGro Engineering Pte Ltd/SH6503J/30/10/2024 14:00. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

2759.00  
 -20%  
 2207.20 + 155 nett = 2362.20

# Estimates on Miscellaneous Items

No Qty Particulars

Amount

## Miscellaneous Items

1	1	OD/TP Case (Insurer)	12.00 /
<b>Sub Total (\$\$)</b>			<b>12.00</b>

# Estimates on Labour

No Particulars

Lab.Type

Amount

## Labour Items

1	PANEL BEATING	New	1149	1,600.00
2	SPRAYPAINT CHARGES	New	1680	1,800.00
3	TUFF KOTE	New	20	50.00
4	CHECK WIRING	New	30	50.00
5	TRANSFER DOOR PARTS	New	30	120.00
6	REMOVE/REFIX REVERSE SENSOR	New	X	50.00
7	TOWING CHARGES	New	3017 Bill	105.00
<b>Gross Labour Cost (\$\$)</b>				<b>3,775.00</b>

ComfortDelGro Engineering Pte Ltd/SH6503J/30/10/2024 14:00. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5379.20

L/S - 4303.36  
= 4300

Steve (LKK)

1/11/24, 3.00pm

in IL

L/S

By AE Spg

5 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_