



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24110011/Avh3e2(N)

Date: 28/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBT 8470U	Veh. Inspected	SNA 2938K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1302079-002	Excess (\$)	0.00
Assign From	RAJESWARY	Assign Date	01/11/2024

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216I GT	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA2D920005E91557	Colour	WHITE
Odometer	107299 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35 R19	FALKEN	6 mm
L/H Front Tyre	235/35 R19	FALKEN	6 mm
R/H Rear Tyre	235/35 R19	FALKEN	6 mm
L/H Rear Tyre	235/35 R19	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/10/2024	Inspect Date / Time	01/11/2024 (01:33 PM)
Survey held at	ELITE AUTO RESTORATION PTE LTD 23 KAKI BUKIT AVE 4 #04-01, AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**