

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|--|----------------------|--|-----------------|-----------------------|--|
| MS | INCOME INSURANCE LTD | | Ref: | CS/INC24110012/Uvh3e2 | |
| | 75 BRAS BASAH R | | Date: | 19/11/2024 | |
| | INCOME CENTRE | SINGAPORE 189557 | Code: | INC | |
| 1. | | | | | |
| •• | Insured Veh. | YQ 9818M | Veh. Inspected | SNL 7789H | |
| | Policy No. | - | Coverage | 0 | |
| | Claim No. | MT/1301924-002 | Excess | \$0.00 | |
| | Assign From | JULIE MANGUBAT | Assign Date | 01/11/2024 | |
| 2. | 2. Vehicle Details | | | | |
| | Make & Model | NISSAN NOTE (A) | c.c | 1198 | |
| | Engine No. | HR12205915J | Year of Reg. | 28/09/2018 | |
| | Chassis No. | JN1TAAE12Z0982235 | Colour | BLUE | |
| | Odometer | 96113 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | General | GOOD | |
| | Modification(s) | RIMS: SPORTS RIM | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance (mm) | |
| | R/H Front Tyre | 185/65R15 | CITY TRAXX | 6 | |
| | L/H Front Tyre | 185/65R15 | CITY TRAXX | 6 | |
| | R/H Rear Tyre | 185/65R15 | CITY TRAXX | 6 | |
| | L/H Rear Tyre | 185/65R15 | CITY TRAXX | 6 | |
| 4. Description of Damages | | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 29/10/2024 | Inspection Date | 01/11/2024 (10:59) | |
| | Survey held at | T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883 | | | |
| 5a. | 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. Estimate Days of Repair | | | | | |

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days