



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE MANGUBAT

Ref: CS/INC24110013/Aqh3e2(N)

Date: 28/02/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 1772H	Veh. Inspected	SLA 2046H
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1301524-002	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	01/11/2024

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WVWZZZAUZGW124928	Colour	WHITE
Odometer	136317 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	ATLANDER	6 mm
L/H Front Tyre	205/55 R16	ATLANDER	6 mm
R/H Rear Tyre	205/55 R16	ATLANDER	6 mm
L/H Rear Tyre	205/55 R16	ATLANDER	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/10/2024	Inspect Date / Time	01/11/2024 (01:27 PM)
Survey held at	ELITE AUTO RESTORATION PTE LTD 23 KAKI BUKIT AVE 4 #04-01, AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**