ASS. REC. BY: REF: 167/	
Kennerh AS	SIGNMENT
From	Veh No: 5M71429 A Yr Regn: 04, 21
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD ITP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toy Privs c.c 1798
at Workshop m/s Tons C6b	Colour M.P. White AC: Insured / Std / NI / NA
of	Sp.Reading 32/089 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: JTO/CB3FU903093842
Claims No.	Gen. Cohd: Good / Fair / Poor / Burnt
	Steering: Inorder / Jammed / Leaked / Burnt or
	Brake: Inorder / Jammed / Leaked / Burnt or
(Cfient's Record)  Make of Veh:	named a second as
many VI FSII.	Modi: NII / S/Rim / STD A/Rim or
	Tyre Stree: Growdride 195/65R15
(Policy Condition)	R: Washi —
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: 8 //2/C	_ Front Rear ()
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm 'R/Bal. 0 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 5 mm L/Bal. mm
Est. Repairs: 03 days Res.: Yes or No	D.O.A. 29/10/24 D.O.I. 1/11/2024
Lum Sum: 20% 3 Val.: Yes or No	Survey held at
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	ols in
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	
· · · · · · · · · · · · · · · · · · ·	
The second of th	
K.	
	The state of the s
	A
	THE PROPERTY OF THE PROPERTY O
Onto/Time, File Pass to? Prell. Report	Days Of Repair:
i): Final Report	Resurvey No. of Trip: Survey Fee:
Outo/Time, File Return to?	Transportation
Add Fee	
Add Fee	
	: Interview (\$ ), Findow
Report Format :	Tech Invs (\$ ) Others
ump Sum / I.B.I: (\$	Weekend (\$
and the second of the second o	
	1074L

Not Nothers

## LAD2410-020

## **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMZ1429A

SMZ1429A Vehicle No.: JTDKB3FU903093842 Chassis No.: 201603575K Co UEN: 0 1 NOV 2024 TOYOTA Vehicle Make: **PRIUS GEN 4** Vehicle Model: 29/10/2024 Date of Accident: SHA9484C/MSFCI Third Party Insurer: 13/4/2021 Date of Registration:

	PART		Rulem	
1	COVER, FRONT BUMPER	\$		653.31
1	ABSORBER, FRONT BUMPER ENERGY	\$		100.91 X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	_	902.16 1
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	_	100.49 X
1	SUPPORT, RADIATOR, UPPER RH	\$		99.33 X
1	MOULDING, FRONT BUMPER SIDE, RH	\$	i h	120.86
1	COVER, FRONT BUMPER HOLE, RH	\$	,	38.22 ×
1	GRILLE SUB-ASSY, RADIATOR	\$		532.88 🗶
1	GRILLE, RADIATOR, LOWER NO.1	\$	•	224.70 X
1	JAR ASSY, WINDSHIELD WASHER	9	•	276.15 X
1	WHEEL, DISC	9	\$ 114	2,554.70
1	ABSORBER ASSY, SHOCK, FRONT RH	,	\$	596.19 7
1	SUPPORT SUB-ASSY, FRONT SUSPENSION, RH		\$	298.10 7
1	JOINT ASSY, LOWER BALL, FRONT RH		\$	331.80 7
1	KNUCKLE, STEERING, RH		\$	836.64
1	FENDER SUB-ASSY, FRONT RH		\$ n	1,236.69 🗶
1	LINER, FRONT FENDER, RH		\$ 5-	255.36 ^
1	EMBLEM, SIDE PANEL, RH		\$ M	- 00.00
1	UNIT ASSY, HEADLAMP, RH		\$ 601	3,325.56
	•	TOTAL	\$ 1	2,552.93
		25%	\$	3,138.23
			\$	9,414.69

## **Special Nett**

## **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

### **SMZ1429A**

1	FRT BUMPER CLIP
1	FENDER LINER CLIP
1	FRT BUMPER SIDE RETAINER CLIP

TOTAL PARTS	\$ 9.0	609.69	_
TOTAL	\$ 195.00		
	\$ NN	65.00	×
	\$ NN	65.00	X
	\$		born

NA

### **LABOUR**

To Rust-Proofing and apply undercoat Of Th	ne Affected A	reas.

\$

\$

\$

111

250.00 X

Putty And Spray Painting Of The Affected Portion.

4

1,800.00 44d

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

Nn 380.00 X

To Check Electrical Lighting Concerned.

170.00 20/

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

2,000.00 4001

To check steering geometry and computer wheel alignment

220.00 601

To transfer of rear fender panel fittings, attachment and perform water seepage test.

TOTAL \$

*√*~ 170.00 X 4.990.00

Over All Total \$

\$ 14,599.69

(PART-BY-PART) Repair Days

87 Days

3 days

# LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# **©** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- E. Ruy IBISE reporting may be referred to the Police for Investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

30/10/2024 11:48 (SGT) **Date of First Submission** Reported by **Actual Driver** 29/10/2024 20:15 (SGT) **Date of Accident Exact Location of Accident** Singapore

JURONG TOWN HALL RD BEFORE BOON LAY WAY **Additional Location Information** 

Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

SMZ1429A Vehicle Registration Number

INSURED/POLICYHOLDER

Yes Is company? TRANS LEASING PTE LTD Name Of Registered Owner 201603575K Company Reg No claims@transcab.com.sg **Email Address** (Phone) +65-62876666 **Mobile Phone No** 

**VEHICLE PARTICULARS** 

Alternative Phone No

Toyota Manufacturer **Prius** Model Variant

Exact purpose for which vehicle was being used at time of Private hire

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

**Transmission** CC

Vehicle Fuel First Regisration Date

Chassis no Effective Date/Time of Ownership

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number Income Insurance Limited 5147264458

No - Claiming third party

Private hire

Auto

1800

DRIVER



### SKETCH PLAN

### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilfful misrepresentation or withholding of material facts may allow insurance companies to <u>reoudjate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Siggapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if trillor is not by collected) / Da 8. Time 30/10/2024

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card) Muhammad Sumardi Bin Mohd Affandi S005530

Sketch Plan

11:25hrs

S995530

A-SMZ1429A

B-SHA9484C

JURONG TOWN

HALL RD

BEFORE BOON

LAY WAY