

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	CE LTD		Ref:	CS/INC24110043/Aqh3e2(N)	
	75 BRAS BASAH R	OAD BINGAPORE 189557		Date:	23/01/2025	
	ATTN: EILEEN LEE			Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKU 7752B	Veh. Inspected	i	SLZ 1436R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1300685-002	Excess (\$)		0.00	
	Assign From	EILEEN LEE	Assign Date		04/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA JAZZ	c.c		1317	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	GK31316462	Colour		WHITE	
	Odometer	89308 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	195/65 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	195/65 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	195/65 R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	19/10/2024	Inspect Date /	Time	04/11/2024 (03:14 PM)	
	Survey held at	CHIA AUTO SERVICES PTE LTI)			
		23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					