



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24110046/Unp3e2
50 RAFFLES PLACE #03-03	Date:	12/11/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6934K	Veh. Inspected	GX 72H
Policy No.	-	Coverage	0
Claim No.	CMTD2403505/THE	Excess	\$0.00
Assign From	THELMA	Assign Date	04/11/2024

2. Vehicle Details

Make & Model	NISSAN CABSTAR (M)	C.C	2953
Engine No.	ZD30017598N	Year of Reg.	31/05/2017
Chassis No.	JN1SC2F24Z0859480	Colour	SILVER
Odometer	171893 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	DUNLOP	6
L/H Front Tyre	195R15	DUNLOP	6
R/H Rear Tyre	165R13 (D)	DUNLOP	6/6
L/H Rear Tyre	165R13 (D)	DUNLOP	6/6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/10/2024	Inspection Date	04/11/2024
Survey held at	IMPERIUM AUTOMOTIVE - 25 KAKI BUKIT ROAD 4 #01-47 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days