



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24110050/Avp3e2
(BUDGET DIRECT INSURANCE)	Date:	23/12/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 3608X	Veh. Inspected	SLJ 3560K
Policy No.	P11073937R00	Coverage	0
Claim No.	C10032590/CH	Excess	\$0.00
Assign From	NG CHEN HOW	Assign Date	04/11/2024

2. Vehicle Details

Make & Model	HONDA HRV	C.C	1496
Engine No.	L15B4531218	Year of Reg.	07/12/2016
Chassis No.	JHMRU1810GX201217	Colour	WHITE
Odometer	117079 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/60 R16	DUNLOP	6
L/H Front Tyre	215/60 R16	DUNLOP	6
R/H Rear Tyre	215/60 R16	DUNLOP	6
L/H Rear Tyre	215/60 R16	DUNLOP	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/11/2024	Inspection Date	04/11/2024
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days