

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/11/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SBS3200X
Case Reference Number	BUS/10/24/8013
Registration Date	8/30/2012
Company Type	SMRT Buses Ltd
Make	VOLVO
Model	B9TL
Name of Driver	K M A Kader Husain S/O Mohd Ab
Type of Accident	Side Swipe
Accident Date and Time	10/22/2024 10:00 AM
Accident Reported Date and Time	11/3/2024 9:47 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC,if any	SBS3200X - LEFT FRONT PORTION PD1064Z (TP) - INSURED WITH INDIA
Prepared Date and Time	11/4/2024 10:57 AM
Chassis Number	YV3S4P920CA157294
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$1,617.19	\$0.00
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$4,415.19	\$0.00
Lump Sum Total	\$4,400.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	04/11/2024 11:04 AM	
Signature		
Remarks		

Steve (LKK)
04/11/24, 4.30 pm
Without Prejudice
L/S
Resurvey After Spray
3 days

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/11/2024

User ID : choonhwee03

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				1060		
Total Labour			\$1,590.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$708.00				616		
Total Spray Painting & Panel Beating			\$708.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
TOWING CHARGE			\$500.00				/ Nec (Bill)		
Total Other Costs			\$500.00						
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6012093			DOME,FRONT:LOWER,C LASS 2,FOR VOLVO B9TL	1.00	\$3,391.95	100.00	\$0.00	Repair	X Repair
6012097	Body	ATP-02807	N/S CORNER DEFLECTOR	1.00	\$328.33	10.00	\$295.50	Replace	/ BR
6012099	Body	ATP-02812	FRT N/S LIGHT BEZEL	1.00	\$298.28	10.00	\$268.45	Replace	/ MIS
4006313			PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	/ Nec
4006314			SEALANT SIKAFLEX	3.00	\$37.00	0.00	\$111.00	Replace	/ Nec
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	/ Nec
6012071	GLASS	GWC-00487	MILLENN N/S 1/4 GLASS	1.00	\$165.88	10.00	\$149.29	Replace	/ BR
6012094	Body	ATP-03155	N/S CORNER BUMPER	1.00	\$974.78	100.00	\$0.00	Repair	/ BR
		0182201	3rd MIRROR BLIND	1.00	\$232.50	10.00	\$209.25	Replace	/ MIS
		MEXR-0027-00	MIRROR VIEW 2 GLASS	1.00	\$270.00	10.00	\$243.00	Replace	/ MIS
		G0212502	MIRROR EXTERIOR LONG ARM	1.00	\$650.00	10.00	\$585.00	Replace	/ MIS
Total					\$6,508.72		\$2,021.49		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									