



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24060250/Aqh3m4
50 RAFFLES PLACE #03-03	Date:	22/08/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EY 64A	Veh. Inspected	SMU 874E
Policy No.	-	Coverage	0
Claim No.	CMTD2402087/GPL	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	25/06/2024

2. Vehicle Details

Make & Model	TOYOTA LEXUS ES250	C.C	2487
Engine No.	A25A5389317	Year of Reg.	29/07/2020
Chassis No.	JTHB11B1802026396	Colour	WHITE
Odometer	51804 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/45R18	MICHELIN	6
L/H Front Tyre	235/45R18	MICHELIN	6
R/H Rear Tyre	235/45R18	MICHELIN	6
L/H Rear Tyre	235/45R18	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/06/2024	Inspection Date	26/06/2024
Survey held at	CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #02-03A AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days