



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: ENG HUEY HUEY

Ref: CS/INC24110064/Avp3e2(N)

Date: 24/04/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMA 8124P	Veh. Inspected	SMU 8769Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1302612-002	Excess (\$)	0.00
Assign From	JULIET KOH	Assign Date	05/11/2024

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN GOLF	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WVWZZZAUZFW193527	Colour	GREY
Odometer	324707 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40 R18	GOODYEAR	6 mm
L/H Front Tyre	235/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	235/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	235/40 R18	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/11/2024	Inspect Date / Time	05/11/2024 (03:06 PM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------