



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN LEE

Ref: CS/INC24110069/Avp3e2(N)

Date: 03/01/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YQ 9626A	Veh. Inspected	SLM 7168T
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1302517-001	Excess (\$)	0.00
Assign From	JURAIDAH ABBAS	Assign Date	05/11/2024

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA FIT	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK31224506	Colour	BLUE
Odometer	120682 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	HANKOOK	6 mm
L/H Front Tyre	185/65 R15	HANKOOK	6 mm
R/H Rear Tyre	185/65 R15	HANKOOK	6 mm
L/H Rear Tyre	185/65 R15	HANKOOK	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	01/11/2024	Inspect Date / Time	05/11/2024 ( 04:20 PM )
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days