# ACCIDENT INVOLVING LUV (MID 36140) AND CIVILIAN TRAILER (XB33K/TRC2348E) AT JURONG ISLAND CHECKPOINT ON 4 NOV 2024 AT ABOUT 0807HRS




Figure A-1: MID36140 Passing Through Jurong Island Checkpoint

The two-way traffic out from the slip road was converted to one way, hence vehicles were formed up on the same direction on both lanes to exit the Jurong Island Checkpoint.




Figure A-2: MID36140 Exiting Jurong Island Checkpoint




Figure A-3: MID36140 Advancing Pass the Stop Line Without Stopping




Figure A-4: MID36140 Making the Right Turn




Figure A-5: MID36140 Came into Contact with Civilian Trailer XB33K TRC2348E



Figure B-1: Front View of MID36140



Figure B-2: Rear View of MID36140



Figure B-3: Left Side View of MID36140



Figure B-4: Right Side View of MID36140



Figure B-5: Zoomed-in View of MID36140

Damage assessment: MID36140 with dented left side front fender



Figure B-6: Zoomed In View of XB33K / TRC2348E



Figure B-7: Contact point of XB33K / TRC2348E

 $\frac{Damages\ Assessment:\ Damage\ to\ right\ rear\ tire\ of\ civilian\ trailer\ XB33K\ /}{TRC2348E}$ 

OTATEMENT OF		STATEMEN	T OF DR	RIVER/WITH	ESS				
STATEMENT OF	PTE AMOS LIM MU EN ALIASES								
NRIC NO.	oio	AGE	21		MA	LE/FEMA	LE	MALE	-
EMPLOYMENT	ENLISTER	DRIVING LICENSE NO	SAF/T	PT / T/00666/2	NA W	TIONALIT	ry S	INGAPOREA	N
DIALECT	-111-	LANGUAGE SPOKEN	100000	LISIT	TE	L NO			
ADDRESS		1							
INTERPRETED BY		R	ANK	TIME		DATE		SIGN	
RECORDED BY		R	ANK	TIME		DATE		SIGN	
closure brocking correct alternative incorrect. White I was momentaril This higheston cause point: As a resurrent of the property of the prope	sed one to	mich de 16	1)	The region	) un	erimin 0	- LIE INE A	11 000	retrust 5
point. As a resulting to py	1 00000	ac some in	-1 LESTA	leading m. Wheat of	a a	nicle to	overy Clas	se 5 ta	tum

Figure C-1: Statement of Driver

#### SINGAPORE ARMED FORCES

#### STATEMENT OF DRIVER/WITNESS

STATEMENT OF	3SG CHEE LEE KANG			ALIASES	
NRIC NO.	852E	AGE	20	MALE/FEMALE	MALE
EMPLOYMENT	NSF	DRIVING LICENSE NO		NATIONALITY	SINGAPOREAN
DIALECT		LANGUAGE ENGLIS SPOKEN		TEL NO	
ADDRESS					
INTERPRETED BY		RANK	TIME	DATE	SIGN
RECORDED BY		RANK	TIME	DATE	SIGN

On 041124, at around 0820hrs, I, 3SG CHEE LEE KANG, T 852E, was the Vehicle Commander for LUV MID36140, which rear-ended a civilian oil tanker while performing a right turn.

In the vehicle were 3SG LEE KANG (Vehicle Commander), PTE AMOS (Transport Operator), 3SG JULIAN, CPL ASWIN, CPL CHIN ANN and CPL CHUN KIT. We were the incoming shift to replace the current duty shift at Jurong Island Ops Centre (JIOC).

Before moving off, I asked the TO if I had to approve the MTRAC on Mobius. The TO replied that it was not necessary as the previous VC already approved it, and that it was sufficient. Nevertheless, I verbally checked with the TO if he was sufficiently rested and familiar with the route to JIOC. No pre-route brief was conducted as I believed the driver was familiar and experienced.

Prior to entering the JGL exit checkpoint, I checked my phone for ops-related messages for a short while as I received multiple notifications during the ride. I then switched it off once I was done and did not use my phone for the remainder of the trip.

We then reached the joining road which requires a right turn to join the main road. The LUV stopped briefly at the STOP marking, and the TO assessed an approaching motorcycle that appeared to be hesitant and slowing down. Based on the situation, the TO decided to proceed forward. Despite knowing that our LUV is to give way to vehicles travelling straight, I felt that intervening at that moment could have disrupted the TO's judgement, potentially leading to a more dangerous situation, like a collision with the motorcycle. Given the circumstances of the situation, I internally agreed with the TO's decision to proceed as I felt it was sound and

Figure C-2: Statement of VC

logical.

After moving past the STO	P marking, the TO attempte	d to turn right to join into th	e outbound lane. From my
seating position, I could r	not see that the LUV was on	a collision course with the oi	I tanker until only 0.5 to 1
seconds before the imp	act. When I realised that we	were in close proximity to the	he tanker, I immediately
alerted the TO. Unfortunat	ely, by that time, there was	likely insufficient time to per	form any corrective action.
DATE	5 NOV 24	SIGNATURE OF DRIVER/WITNESS	

All statements and further statements are to timed and dated. Witness will be rewarned immediately prior to the recording of further statements. Statements and further statements will be signed by the Recording Officer and Interpreter. Statements of witness must be signed by the Witness.

SAF 1201

Figure C-3: Statement of VC (Continuation)





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Details of Vehicle Involved

Type

Pick-up

Trailer

Vehicle No.

MID36140

TRC2348E

1 of 3 Report No. T/20241104/7134

REPORT OF	A TRAFFI	C ACCIDENT						
Date/Time Report Made: 04/11/2024 20:09		Vide Report No.:			\$	Station Diary No.:		
Informant's I		rs						
Name of Informant: AMOS LIM MU EN			Address:					
ID Type / ID No.: NRIC NO / 701D			Contact No.: Home/Office: Mobile:					
Nationality: SINGAPORE CITIZEN			Email:					
Sex: Male	Age: 21	Date of Birth: 22/07/2003	Type of Informant: Driver					
Race: Chinese			Langua English					
Occupation: Other car and light goods vehicle drivers			Driving Licence Information: Class: Date of Expiry:					
General Infor		f the Accident						
Type of Acc		Non-Injury Government Vehicle		Drink Drive: No	Date/Time of Accide 04/11/2024 08:05	ent:	Type of Location: T-Junction	
Location:								
JURONG PI	IER ROA	D						
Weather: Drizzling			Road Surface: Wet					
Traffic Flow: Dual Carriage Way			Traffic Control: Not Controlled				Traffic Volume: Heavy	
Type of Collision: Moving Vehicle Against - Parked Vehicle						Anyone conveyed by ambulance:		

Make Model Color Condition No of Passenger

Slightly Damaged 0

Figure D-1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 3 Report No. T/20241104/7134

#### CONTINUATION OF REPORT

Passenger						
Name	CHEE LEE KANG			ID No.		352E
Related Vehicle	MID36140 (Pick-up)			Contact No.		
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	scharge NIL		L	
lo. of Days granted Medical Leave (MC) NIL			Degree of Injury NIL			
Driver						
Name	AMOS LIM MU EN			ID No.		701D
Related Vehicle	NIL			Contact No.		
Hospital/Clinic	NIL			Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	NIL Date Di			arge	NIL	1
No. of Days grant	of Days granted Medical Leave (MC) NIL			Degree of Injury NIL		

#### Brief Details.

I, 701D, PTE Amos Lim Mu En am a full time National Serviceman, serving in the Singapore Armed Forces as a transport operator. In this incident, I was operating vehicle MID 36140, accompanied by 3SG Chee Lee Kang(8SIR), on JGL Ops B tasking, en route to the JIOC for shift change at 0730 hours. As I approached the checkpoint, I encountered a closure blocking the usual exit route from Jurong Island. Believing I had chosen the correct alternate route, I deviated from the intended path, though this turned out to be incorrect. While preparing to exit by making a right turn toward the adjacent road, I was momentarily distracted by an oncoming motorcycle, uncertain whether it would stop. This hesitation caused me to misjudge the turn, leading my vehicle to overshoot the turning point. As a result, I collided with the rear right wheel of a stationary Class 5 trailer that was waiting to proceed. (TRC2348E)







3 of 3 Report No. T/20241104/7134

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 04/11/2024 20:09
Officer In Charge Of Case: TP / AEIT / LEE GUANG HUI Contact No.: 65476414	Classification Of Case:
Fig	ure D-3