



Your Ref: -

Date: 21st Nov 2024

Our Ref: CS1/QW24110102/Evh3e2

M/s Comfortdelgro Engineering Pte Ltd

59 Loyang Drive
Singapore 508969

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SH 6389Y
ACCIDENT DATE: 06/03/2024**

We thank you for your instruction on 04/11/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SH 6389Y from M/s Comfortdelgro Engineering Pte Ltd.
- b) Singapore Accident Statement and Police Report of Vehicles SH 6389Y.
- c) Colour damaged vehicle photographs of SH 6389Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SH 6389Y
Make & Model	: Hyundai AE Ioniq Hev FL 1.6 DCT
Chassis Number	: KMHC851CVLU189970
Year of Registration	: 2019
Engine Capacity	: 1580 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.