MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

SJE:	Vehicle Nos :	SLX 4337J
Date of Survey :	Made:	Subaru
Date of ReSurvey:	Model :	Forester 2.0I-L CVT
Contacts:	Chassis No :	JF1SJ5KC5JG105732
* AGREED Cost Of Repair and Repair Day/s with		
Amount:	Working Day:	

Nos.	PARTS	Qty	10.00	Unit S\$	7	TOTAL S\$
1	Front Bumper / CR	1	\$	610.50	\$	610.50
2	Front Bumper Tow Cover X	1	\$	10.20	\$	10.20
3	Front Bumper Lower Grille X	1	\$	105.00	\$	105.00
4	Front Bumper Side Retainer RH 🗡	1	\$	42.00	\$	42.00
5	Front Bumper Side Retainer LH / BR	1	\$	42.00	\$	42.00
6	Front Bumper Bracket RH X	71	\$	16.00	\$	16.00
7	Front Bumper Bracket LH X	1	\$	16.00	\$	16.00
8	Front Bumper Fog Lamp Garnish RH 🗡	1	\$	48.80	\$	48.80
9	Front Bumper Fog Lamp Garnish LH × 1 \$ 48.80 \$					48.80
10	Front Bumper Fog Lamp Side Garnish RH 🗡	1	\$	23.00	\$	23.00
11			23.00			
12	Front Bumper Fog Lamp RH X 1 \$ 282.00 \$		282.00			
13	Front Bumper Fog Lamp LH X 1 \$ 282.00 \$		\$	282.00		
14	Front Bumper Nozzle Cover RH × 1 \$ 65.50 \$		65.50			
15	Front Bumper Nozzle Cover LH X 1 \$ 65.50 \$		65.50			
16	Front Bumper Nozzle Washer RH × 1 \$ 94.10 \$		94.10			
17	Front Bumper Nozzle Washer LH × 1 \$ 94.10 \$		94.10			
18	Front Bumper Sponge X	1	\$	142.40	\$	142.40
19	Front Bumper Reinforcement X	1	\$	325.60	\$	325.60
20	Front Grille Assembly Upper / (VI)	1	\$	170.60	\$	170.60
21	Front Grille Assembly Lower Chrome Moulding	1	\$ X	185.60	\$	185.60
22	Front Grille Assembly $$	1	\$	357.50	\$	357.50
23	Front Grille Upper Bracket	1	\$	21.60	\$	21.60
24	Front Grille Lower Bracket	1	\$	32.20	\$	32.20
25	Front Headlamp Assembly RH 😾	1	\$	2,380.00	\$	2,380.00
26	Front Headlamp Assembly LH / RR	1	\$	2,380.00	\$	2,380.00
27	Front Bonnet $\times \mathcal{K}$	1	\$	916.50	\$	916.50

28	Front Bonnet Hinge RH X	1	\$	54.40	\$	54.40
29	Front Bonnet Hinge LH	1	\$	54.40	\$	54.40
30	Front Bonnet Lock Assembly X	1	\$	75.50	\$	75.50
31	Front Bonnet Insulator Centre X	1	\$	169.20	\$	169.20
32	Front Bonnet Insulator RH	1	\$	47.00	\$	47.00
33	Front Bonnet Insulator LH $^{\chi}$	1	\$	47.00	\$	47.00
34	Front Door LH X	1	\$	884.30	\$	884.30
35	Front Fender LH / PD	1	\$	327.50	\$	327.50
36	Front Fender Inner Upper Garnish LH 🗡	1	\$	22.50	\$	22.50
37	Front Fender Inner Cowling LH / TN	1	\$	131.00	\$	131.00
38	Front Shock Absorber LH	1	\$	367.60	\$	367.60
39	Front Lower Arm LH	1	\$	527.80	\$	527.80
40	Front Knuckle Arm LH	1	\$	424.80	\$	424.80
41	Front Wheel Bearing LH	1	\$	382.20	\$	382.20
42	Front Support Panel X	1	\$	381.60	\$	381.60
43	Aircon Condenser X	1	\$	654.90	\$	654.90
44	Radiator Assembly X	1	\$	915.80	\$	915.80
45	Radiator Shroud ×	1	\$	108.80	\$	108.80
46	Fan Blade X	1	\$	55.50	\$	55.50
47	Fan Motor Assembly	1	\$	282.00	\$	282.00
			Av va	CITIL	4	44.504.30

Parts Sub Total : \$ 14,694.30 20% Discount \$ 2,938.86 PARTS TOTAL : \$ 11,755.44

Nos.	SPECIAL NETT	Qty	30.00	Unit S\$	TOT	ALS\$
1	Front Number Plate X	1	\$	50.00	\$	50.00
2	Front Bumper Clips - Set / /	1	\$	50.00	\$ 30	50.00
3	Front Headlamp Clips - Set 💢	1	\$	50.00	\$	50.00
4	Front Grille Assembly Clips - Set 🖊 🎢	1	\$	50.00	\$ 20	50.00
5	Front Support Panel Top Garnish Clips - Set $^{ imes}$		\$	50.00	\$	50.00
6	Front Fender Inner Cowling Clips - Set / M	1	\$	50.00	\$ 20	50.00
7	Front Bonnet Sealant $ \chi $		\$	150.00	\$	150.00
8	Front Fender LH Sealant X		\$	150.00	\$	150.00
9	Front Support Panel Sealant 💢		\$	150.00	\$	150.00
10	Front Door LH Sealant 🛭 🗡	1	\$	150.00	\$	150.00
11	Front Wheel Rim LH / (VI)		\$	1,500.00	\$ 800	1,500.00
12	Front Tyre LH X	1	\$	450.00	\$ 941.4	450.00
13	Front Bumper Lower Spoiler - Aftermarket /		\$	1,200.00	\$ 700	1,200.00
14	Radiator Coolant X	1	\$	50.00	\$	50.00
		SPECIA	LN	ETT TOTAL:	\$ A CHANGE	4,100.00



Nos.	LABOUR	TOT	ALS\$
1	To Panel Beat, Remove & Refix Parts	\$ 400	1,600.00
2	To Spray Paint Affected Areas	\$ 600	1,400.00
3	Wiring & Bulb Check	\$ 30	100.00
4	To Transfer Front Door LH Mechanism	\$ X	150.00
5	To Remove & Refix Aircon Condenser & Top up Gas	\$ X	150.00
6	To Remove & Refix Radiator & Pressure Test	\$ X	150.00
7	To Remove & Refix Front Undercarriage	\$!	450.00
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ 80 70	150.00
9	To Conduct Four Wheel Alignment	\$ 80	150.00
10	To apply anti rust on affected parts	\$ 30	100.00
11	To Conduct Water Leak Test	\$ X	100.00
12	To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ X	480.00
	LABOUR TOTAL:	\$	4,980.00

Steve (LKK)
7/11/24, 10.30 on
L/S
L/S
M AL M
5 days

PARTS TOTAL : \$ 11,755.44

SPECIAL NETT TOTAL : \$ 4,100.00

LABOUR TOTAL : \$ 4,980.00

GRAND TOTAL: \$ 20,835.44

LKK Auto Cons Protify the Repairer of the second:

- To resurvey before/after and mainting
- To display damaged part(s) during resurvey
- Parts prices are subject to co matten
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

Mark the Carlot

No. of the second secon



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the eccident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver.

3. Information provided must be as truthful and accurate as possible. Any wifful misrepresentation or witholding of material facts may aflow insurance companies to repudiate policy liability.

4. The issue and ecceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

29/07/2024 18:07 (SGT) **Date of First Submission**

Reported by **Actual Driver**

Date of Accident 24/07/2024 22:00 (SGT)

Exact Location of Accident Singapore

LANE 1 BUYONG RD TOWARDS CTE Additional Location Information

Singapore Country/State of Loss

DETAILS OF OWN VEHICLE

Private use

Vehicle Registration Number **SLX4337J**

INSURED/POLICYHOLDER

Is company? **CHEW ANN PENG** Name Of Registered Owner S7171281H NRIC No DEANPHUA22@GMAIL.COM Email Address

(Phone) +65-90622168 Mobile Phone No

Alternative Phone No

VEHICLE PARTICULARS

Subaru Manufacturer FORESTER 2.01-L CVT AWD SR Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to No - Claiming third party

your vehicle? Vehicle Category Private car Auto Transmission 1995

CC

INSURANCE COMPANY

Direct Asia Insurance (Singapore) Pte Ltd Name of Insurance Company MT/01186276/01 Policy Number / Cover Note Number

DEAN PHUA Name of Driver T0315627Z NRIC No 02/06/2003 Date Of Birth

Occupation

Indoor

Accident report SV10247T0008

Page 1 of 17




· ·	
Driving Pass Date	16/06/2023
Driving experience	1 YEAR AND 1 MONTH
Gender	Female
Mobile Number	(Phone) +65-90622168
Alt. Phone Number	DEANPHUA22@GMAIL.COM
Email Address Address	APT BLK 309A ANG MO KIO STREET 31 #06-341
Address complement	APT BER 309A ANG MO NIO STREET OF WOO
Postcode	562309
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Parent
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	:
GENERAL INFORMATION OF THE ACCIDENT	
T of April 100	Hit and run / Vandalism / Damaged whilst parked
Type of Accident Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	• Was
Number of Passengers (Including Driver)	Yes 1
Has the driver been approached by unknown person(s)	•
soliciting/offering accident claims assistance?	No
Translator's name	. ■
Translator's ID	•
Translator's phone number	
Translator's email	•
Original language used in the statement	• I I I I I I I I I I I I I I I I I I I
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	Yes
Police Station Name	Ang Mo Kio North Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18004849999
Alt. Police Station Phone No	(Fax) +65-62181399
Police Station Address	51 Ang Mo Kio Avenue 9 Singapore 569784
Was notice of intended Prosecution given?	No
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
REFER TO THE POLICE REPORT	
	77.144.164.161
ATTACHMENT(S)	HILL COMPANY OF THE STATE OF TH
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
	and the second s
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number	SFY9779A
Vehicle Manufacturer	•
Vehicle Model	r t einies das i
Vehicle Variant	N

P Accident report SV10247T0008

CS CamScanner

	Vehicle Colour Vehicle Category	Private car
100	Name of Driver	•
	Contact Number Address	:
	Address complement	
	Postcode Insurence Company Name	:
	Nature Of Damage	
	Details of property damaged in accident	•
	No. Of Passenger (Including Driver)	•



Accident report SV10247T0008

Page 3 of 17





Rever to police ((Port	
	Annual Control of the
	A 1881年1月1日 日本 1877年1月1日 日本 1871
larstion Seciare the foregoing particulars are the in every respect	6100
The state of the s	No.
	(C) UEN
Once.	M. T.
yholder's Signature / Date & Time Actual Differ's Signature (if driver is not the po	(Name as in NRIGAD card)

C Accident report SV10247T0008

-

Page 4 of 17



SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accordent to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Actual Drives.
- 3 Information provided must be se truthal and accurate as possible. Any withal misrepresentation or witholding of material facts many allow insurance companies to recuriate color fability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Traific Police Department for investigation.
- 6 This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B Consent under the Personal Data Protection Act (PDPA)

I uncerstand, adknowledge, agree and consent shat:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may lare permitted to collect, use, discisse and for process my personal data/personal information set ext in this (form) and any other personal information provided by me or possessed by my insurer (collectively the Tereonal Information") and discisse and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident and perceively referred to as the "Insurers" insurers insured that, the Monetary Authority of Singapore and any relevant povernment agency/sutbority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my dalms including the settlement of the claims and any necessary investigations relating to the claims;

- (3) investigating the accident and/or my clama;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administrating my claims (Including the mailing of correspondence, statements involves reports or notices to me which could sinvolve discreture of certain personal data about me to bring about delivery of the same se well as on the external cover of sinveloces mail packages it ancier
- (v) conceying with explicable law in administering, processing, handling end/or dealing with my claims

(cole cakely Pe 'Purposes')

(b) all insurents) who have insured vehicle(s) involved in this accident and the Insurents temperature firms, may/are permitted to collectuate, discress end/or process my Personal information for one or more of the above Purposes, and

(c) my Personal information may/can be disclosed by any of the heurers and/or GIA to their third-party service providers or agents (including their lawyers/taw firms), which may be sted outside of \$ ingapore for one or more of the above Purposes

ans.

Policyholder's Signature / Date & Time

1111

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

111111

1111111 ... 1111111

Witnessed by Reporting Centre Personnel
I Name as in NRICAD card)

Sketch Flan



Page 5 of 17

C Accident report SV10247T0008





SINGAPORE POLICE FORCE



Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929 Tel No: 1800-4519999

Report No. 1/20240724/2086

Date/Time Report Mede: 24/07/2024 23:17			Vide Report No.: Station Dia 63				
Informa	nt's Partic	ulare	中心。对于14个沙路或是有一位。	March 15 M			
	Informant:		Address: 309A ANG MO KIO STREET 31 #06-341 SINGAPORE 562:				
ID Type / ID No.: NRIC NO / T0315627Z			Contact No.: Home/Office: Mobile: 90622168				
Nationali SINGAP	ty: ORE CITIZ	EN	Email:				
Sex: Male	Age: 21	Date of Birth: 02/06/2003	. Type of Informant: Oriver				
Race: Chinese			Language:				
Occupation: Student			Driving Licence Information: Class: 3A	Date of Explry:			
	.,	7. 1	1	- 1 0 100 mg 1			

General Inform	nation of the Accide			tools and took down and
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 24/07/2024 22:00	Type of Location Straight Road
Location:				,
BUYONG RO	AD			
Weather:		Road Surface:	•	
Clear		Dry		
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collis Between Mov		wipe - Same Direction		Anyone conveyed by ambulance: No

Details of Ve	hicle involved	114 144	State of the State of the	公司 国际,1445年	图4.25	The State of the S
	Type - F		Model	Color	Conditio	No of Passenger
SLX4337J	Motor car		-		Slightly	1

Details of Person Involved	Water Committee of the
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA







Police Station Of Origin: Ang Mo Klo South N.P.C

81 Ang Mo Kio Avenue 3 SINGAPORE 569929

Report No. 1/20240724/2086

Tel No: 1800-4519999

CONTINUATION OF REPORT

Driver	THE PARTY OF THE P	AND COST COST	ID No.	1	T0315627Z
Name	DEAN PHUA		ID No.		100150212
	The state of the s		Contact No.		90622168
Related Vehicle	SLX4337J (Motor car)		-		
Hospital/Clinic	NIL			•	Class: 3A Date of Expiry: NIL
	18		Driving Licence Explry		
		Date Disc		MIL	and the second second
Date Treatment	ed Medical Leave NIL	Degree of		ML	

Brief Details.
On 24/07/2024 between 2200 hrs and 2211 hrs, I was driving my mother's vehicle (SLX4337J) with my friend as a passenger along Lane 1 of Buyong Road towards CTE and I stopped at the last traffic light just before entering CTE. Brief Details.

When the traffic light turned green, I moved off and a black vehicle, either bearing the Mazda or Honda brand, tried to filter into my lane from my left and hit the front left of my mother's vehicle while filtering into the lane and just sped off afterwards. dist.

I tried to pursue the vehicle but it was too fast and I did not manage to stop it. I do not recognize the registration plate of the vehicle that hit onto me and my mother's vehicle do not have an in-car camera installed at the front of her vehicle. I wish to state that both my friend and I were not injured from this accident and my mother's vehicle suffered some dents on the rim of the front left tyre and also some scratches on the front left bumper which also came out slightly.







3 of 3 Report No. 1/20240724/2086

Police Station Of Origin: Ang Mo Kio South N.P.C 81 Ang Mo Kio Avenue 3 SINGAPORE 569929 Tel No: 1800-4519999

CONTINUATION OF REPORT

	Signature Of Informant:	0	nature of Officer Recording The
Be		W	T 3 ELSON OH CHUAR ONG
	Date/Time: 24/07/2024 23:17		nature Of Interpreter: applicable
	Classification Of Case:	PAUL	cer in Charge Of Case: / HRT / /OHAMMAD ABDILLAH BIN P // Itact No.: 65476902
		PALIL	

CAccident report SV10247T0008

Page 17 of 17

