

JED8141 [SLN7037H] - Submitted by: GSCA Adjusters Sdn Bhd (HQ)



1/35: Front View Left



2/35: Front View Right



3/35: Rear View Left

JED8141 [SLN7037H] - Submitted by: GSCA Adjusters Sdn Bhd (HQ)



4/35: Rear View Right



5/35: Photographs of Damaged Parts



6/35: Photographs of Damaged Parts



7/35: Photographs of Damaged Parts




8/35: Photographs of Damaged Parts



9/35: Photographs of Damaged Parts



10/35: Photographs of Damaged Parts



11/35: Photographs of Damaged Parts



12/35: Photographs of Damaged Parts



13/35: Photographs of Damaged Parts



14/35: Photographs of Damaged Parts



15/35: Photographs of Damaged Parts



16/35: Photographs of Damaged Parts



17/35: Photographs of Damaged Parts



18/35: Photographs of Damaged Parts



19/35: Photographs of Damaged Parts



20/35: Photographs of Damaged Parts



21/35: Photographs of Damaged Parts



22/35: Photographs of Damaged Parts



23/35: Photographs of Damaged Parts



24/35: Photographs of Damaged Parts



25/35: Photographs of Damaged Parts



26/35: Photographs of Damaged Parts




27/35: Photographs of Damaged Parts



28/35: Photographs of Damaged Parts




29/35: Photographs of Damaged Parts



30/35: Photographs of Damaged Parts



31/35: Photographs of Damaged Parts



32/35: Photographs of Damaged Parts



33/35: Odometer Reading

JED8141 [SLN7037H] - Submitted by: GSCA Adjusters Sdn Bhd (HQ)



34/35: Chassis Number



35/35: Engine Compartment