Surveyor:

REF: CS1/CTI24110121/Enh3 (JED 8141)

Special Instruction:

L/SUM : - / REPAIR:15 WORKING DYAS

Third Parties:

Claimant:

Surveyor: GSCA ADJUSTERS SDN BHD

Workshop: SING YEN WORKSHOP(HQ)

ASSIGNMENT (Office)

From (Person): CECILIA LEE of CTI Date/Time: 06/11/2024

Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: JED 8141 Insured: SLN 7037H

at Workshop m/s SING YEN WORKSHOP(HQ) Tel:

of NO 24 JALAN CANGGIH 6, TAMAN PERINDUSTRIAN CEMERLANG 81800 ULU TIRAM, JOHOR DARUL TAKZIM.MALAYSIA.

Policy No: Claim No: SNM24D205264

Sum Insured: Excess:

Make of Veh: D.O.A. 18/09/2024

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: **Confirmed with** **Final Fig** , **days (Red $ / %; Original days)**

Date/Time: 11/11/24 **Submit Final Fig** 3566.42 , 5 **days (Red $** 7155.78 / 66 **%; Original** 15 **days)**

Date/Time	Action/Instruction

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to